Send Correspondence to:

Philip D. Freedman Philip D. Freedman PC 6000 Wescott Hills Way Alexandria, Virginia 22314-4747

Respectfully submitted,

Philip D. Freedman

Reg./No. 24,163

Philip D. Freedman PC Customer Number 25101 6000 Wescott Hills Way

Alexandria, Virginia 22315-4747

(703) 313-0171

Fax: (703) 313-9322

Email: tekesq@tekesq.com

Alexandria, Virginia

Attachments:

Two copies of this document
Specification (53 pages)
Drawings (5 sheets)
Declaration copy
Preliminary Amendment
Power of Attorney copy
Assignment Copy
Amendment Transmittal Letter (with two copies)
Information Disclosure Statement with one Form-1449
Credit Card Payment Form

SEQUENTIAL HIGH THROUGHPUT SCREENING METHOD AND SYSTEM

BACKGROUND

5

10

15

20

25

1. Field of the Invention:

The present invention relates to a sequential high throughput screening (HTS) method and system.

2. Discussion of Related Art:

In experimental reaction systems, each potential combination of reactant, catalyst and condition should be evaluated in a manner that provides correlation to performance in a production scale reactor. Combinatorial organic synthesis (COS) is an HTS methodology that was developed for pharmaceuticals. COS uses systematic and repetitive synthesis to produce diverse molecular entities formed from sets of chemical "building blocks." As with traditional research, COS relies on experimental synthesis methodology. However instead of synthesizing a single compound, COS exploits automation and miniaturization to produce large libraries of compounds through successive stages, each of which produces a chemical modification of an existing molecule of a preceding stage. The procedure provides large libraries of diverse compounds that can be screened for various activities.

The techniques used to prepare such libraries involve a stepwise or sequential coupling of building blocks to form the compounds of interest. For example, Pirrung et al., U.S. Pat. 5,143,854 ostensibly discloses a technique for generating arrays of peptides and other molecules using, for example, light-directed, spatially-addressable synthesis techniques. Pirrung synthesized polypeptide arrays on a substrate by attaching photoremovable groups to the surface of the substrate, exposing selected regions of the substrate to light to activate those regions, attaching an amino acid monomer with a photoremovable group to the activated region, and repeating the steps of activation and attachment until polypeptides of the desired length and sequences are synthesized.

10

15

20

25

According to the teachings of Pirrung, each synthesis requires bringing the array to reaction conditions, which requires time. If multiple synthesis steps are utilized as is often the case, each synthesis step should be carefully controlled to achieve uniform reaction conditions and time. Uniform reaction conditions and time periods are difficult to achieve with batch processing of array plates. Further, it is difficult to define and control reaction time with batch processing, since each array plate must be individually "ramped" to target synthesis conditions and then "backed off" from the conditions upon completing the reaction. Considerable manual manipulation may be required at startup and shutdown in adjusting controls, loading samples and bolting enclosures.

Additionally, a high pressure reactor large enough to hold an array plate would require thick walls that cause a delay in controlling temperature. Adjustment of temperature within the reactor always lags behind adjustment at the temperature control. This can be a serious problem where precise temperature control is required. For example, catalyst reaction studies typically require temperature measurement and control to better than $\pm 2^{\circ}$ C (preferably $\pm 0.5^{\circ}$ C).

There is a need for an HTS method and system to easily conduct multiple syntheses under identical or precisely controlled variable conditions and reaction times.

SUMMARY OF THE INVENTION

Accordingly, the present invention is directed to a method and apparatus for rapid screening of multiphase reactant systems. In one exemplary embodiment, the method includes the steps of sequentially loading a plurality of discrete combinations of reactants into a longitudinal reaction zone; reacting each of the combinations as it passes through the reaction zone to provide a continuously or an incrementally varying reaction product; and sequentially discharging the reaction product of each of combination from the reaction zone as reaction of each combination is completed.

10

15

20

2.5

In another aspect, the present invention is directed to a combinatorial chemical synthesis system, comprising a vessel having a charge port adapted to sequentially receive a plurality of discrete combinations of reactants and a reaction chamber in communication with the charge port and adapted to receive and enclose the plurality of reactant combinations disposed linearly within the chamber. A discharge port is placed in communication with the reaction chamber to sequentially discharge reaction products from the reaction chamber.

BRIEF DESCRIPTION OF THE DRAWINGS

Various features, aspects, and advantages of the present invention will become more apparent with reference to the following description, appended claims, and accompanying drawings, wherein

- FIG.1 is a schematic representation of an aspect of an embodiment of the present invention;
- FIG.2 is a schematic representation of an aspect of an embodiment of the present invention;
- FIG.3 is a schematic representation of an aspect of an embodiment of the present invention;
- FIG.4 is a table of sequences for carrying out an aspect of an embodiment of the present invention; and.
- FIG.5 is a graph showing influence of effects and interactions utilizing an embodiment of the present invention.

DETAILED DESCRIPTION OF PREFERRED EMBODIMENTS

Various embodiments of the present system are capable of fully unattended around the clock operation. Temperature, pressure, reaction time and reactant mix within a vessel reaction chamber can be fully automated to allow complete experimentation within precisely scheduled parameters. Sequential high throughput screening (HTS) methods can be conducted within the tubular reactor. For example, sequentially loaded combinations of reactants can be subjected to a varying parameter of reaction within a reaction zone of the reactor to provide continuously or incrementally varying product. The composition of each sequentially loaded

combination can be controlled along with control of varying parameters of reaction within the reaction zone and sequentially produced products can be detected by a convention detecting means. The detected products can be correlated with the varying parameters of the reaction to provide a nonrandom combinatorial library of product.

These and other features will become apparent from the drawings and following detailed discussion, which by way of example without limitation describes preferred embodiments of the present invention.

10

5

FIG.1 is a schematic representation of an exemplary system 10 for sequential combinatorial chemical synthesis. FIG. 1 shows a system 10 including a sequential loader 12, a reaction vessel 14, a controller 16 and a detector 18. Loader 12 is shown having an encasement 20 enclosing an array 22 of vials 24 and a robotic frame 26 that includes an X-Y positioning arm 28 and an extendable vial manipulator 30.

15

20

Reaction vessel 14 and controller 16 are shown in more detail in FIG.2. Referring to both FIG.1 and FIG. 2, vessel 14 includes a longitudinal reaction chamber 32 having a charge pipe 34 at a chamber first end 36 and a mechanical exit actuator 38 and a discharge pipe 40 at a chamber second end 42. Charge pipe 34 includes a charge port 44 for receiving sequentially loaded vials 24 from loader 12. Charge pipe 34 provides a conveyance for receiving vials 24 and conveying the vials in a sequential fashion to reaction chamber 32. Charge pipe 34 is provided with at least two valves – a charge actuator 46 and a charge gas lock actuator 48 - that create a charge gas lock zone 50. Similarly, discharge pipe 40 includes a discharge port 52 for discharging vials 24 that have been sequentially transported through discharge pipe 40 from reaction chamber 32. In the embodiment shown, discharge pipe 40 is provided with at least two valves – a discharge gas lock actuator 54 and a discharge actuator 56 that create a discharge gas-lock zone 58.

30

25

Further shown in FIG.2 is a gas supply and valving combination that illustrates a preferred feature. A gas pressure generator 60 supplies high pressure gas

via a pipe 62 to charge pipe 34 and via a pipe 64 to charge gas lock zone 50. Also, gas pressure generator 60 supplies high pressure gas via a pipe 66 to discharge gas lock zone 58. Pipe 62 includes a charge lock pressure valve 68 that regulates pressure within charge gas lock zone 50. Pipe 64 includes a vessel valve 70 that regulates pressure within reaction vessel 14. Pipe 66 includes a three way discharge lock pressure valve 72 that regulates pressure within discharge gas lock zone 58 by injecting gas or by releasing pressure via a vent 74 to the atmosphere.

The system can include a controller as shown in FIG.1 and FIG.2. Controller 16 includes a processor 76, which can be a microprocessor, computer or the like. Processor 76 can be controllably connected to any or all of charge actuator 46, charge lock pressure valve 68, charge gas lock actuator 48, vessel valve 70, mechanical exit actuator 38, discharge gas lock actuator 54, vessel valve 70, and discharge actuator 56 via lines 78, 80, 82, 84, 86, 88, and 90 to provide a controlled sequential combinatorial chemical synthesis as hereinafter described.

FIG.1 shows a cut away side view of the reaction vessel 14 showing a stack of vials 24 progressing through longitudinal reaction chamber 32. FIG. 1 also shows an electronic heating jacket 102 encompassing chamber 32. FIG. 3 further shows jacket 102 in combination with a structure for controlling temperature conditions within the chamber 32. The structure includes insulation 104 interposed within jacket 102, a high precision temperature measuring device 106, and a feedback heat controller 108. Examples of the high precision temperature measuring device include a thermocouple, thermistor, or platinum resistance thermometer. Heat controller 108 is attached to the interior of chamber 32 by leads 110. Electronic heating jacket 102 is shown with feedback control via temperature measuring device 106, which can be a probe and heat controller 108. Other combinations can be used to control the temperature in chamber 32 such as a vapor heating jacket with pressure control, so long as the temperature can be controlled to within ±2° C, desirably within ±1° C and preferably within ±0.5° C.

An HTS method can be conducted in the system shown in FIGs.1, 2 and 3. In an exemplary embodiment of the method, an array of catalyst formulations is prepared according to any suitable procedure. For example, one procedure produces a homogeneous chemical reaction utilizing multiphase reactants. In this procedure, a formulation is prepared that represents a first reactant that is at least partially embodied in a liquid. During the subsequent reaction, the liquid of the first reactant can be contacted with a second reactant at least partially embodied in a gas. The liquid forms a film having a thickness sufficient to allow the reaction rate of the chemical reaction to be essentially independent of the mass transport rate of the second reactant into the liquid.

Each thin film formulation is deposited into a vial 24 to provide an array of reaction vials 24. Vial 24 is preferably formed of a rigid material that is chemically inert in the reaction environment. An example of an acceptable vial for many reactions is a glass vial. When dealing with liquids with low vapor pressures or with lengthy reactions, it may be desirable to provide a covering, such as a selectively permeable cap 16 or a septum (not shown) incorporating a feed tube or needle disposed such that a gas is allowed to move freely into and out of vial 24 while depletion of liquid by evaporation is minimized. This arrangement allows an external pressure source to act upon the gas in the reactant environment while evaporation of liquid is limited. In most applications, suitable materials for the cap include polytetrafluoroethylene (PTFE) and expanded PTFE. A suitable cap for use with 2 ml glass vials is "Clear Snap Cap, PTFE/Silicone/PTFE with Starburst, 11mm", part no. 27428, available from Supelco, Inc., Bellefonte, Pennsylvania.

The sequential loader 12 can be coordinated by controller 16 with a valving and actuator sequence described in the table of FIG.4. With reference to FIG.4, at commencement of operations, charge valve actuator 46 and discharge actuator 56 are open and the mechanical exit actuator 38 is deactivated (off); charge gas lock valve 46, charge lock pressure valve 68, vessel pressure valve 70 and discharge gas lock actuator 54 are closed and the three way gas lock valve 72 is in a vent position. The array of vials is positioned within sequential loader 12. Extendable X-Y positioning

10

15

20

25

30

arm 28 grasps a vial 24 from the array 22 and positions the vial above charge port 44. Vessel pressure valve 70 is opened. A first vial from the array is charged by positioning arm 28 through open actuator 46 into charge gas lock zone 50 and the actuator is closed. Charge lock pressure valve 68 is opened and the charge lock zone 50 is pressurized to a pressure to match a reaction pressure within reaction chamber 32.

When pressure in charge lock zone 50 matches the reaction chamber pressure, charge lock pressure valve 68 is closed and charge gas lock actuator 48 is actuated to advance vial 24 into reaction chamber 32 and the actuator is closed. At this time, charge valve actuator 46 can be opened and charge gas lock zone 50 vented.

Vial contents are subjected to temperature and pressure reaction conditions within reaction chamber 32. Discharge actuator 56 is closed and three way discharge lock valve 72 is positioned to admit pressured gas from gas pressure generator 60 into discharge gas lock zone 58. Upon completion of reaction of the vial contents, mechanical exit actuator 38 is activated. Mechanical actuator 38 extends an arm immediately above vial 24 to prevent upper vials from dropping when a discharged vial drops from the chamber 32 into discharge gas lock zone 58. Discharge gas lock actuator 54 is then closed. Mechanical actuator 38 withdraws the arm, allowing vials above discharged vial 24 to drop so that the stack is now at the bottom of the tube.

Discharge gas lock zone 58 is depressurized by venting via three way valve 72 and discharge actuator 58 is opened to discharge vial 22 from zone 58 and thence from discharge pipe 40 to detector 18.

The above valve and actuator cycling procedure has been described with reference to processing of a single vial 22. However, a plurality of vials can be processed by repeating the FIG.4 steps 2-8 a plurality of times to fill reaction chamber 32. Once chamber 32 is filled, then steps 2-16 are repeated to discharge a vial and to charge a vial to the reaction chamber.

Referring again to FIG.1, the system also includes detector 18, which comprises a vial ejector 92 to direct a vial 24 from the reaction vessel discharge port 52 to a position within a vial array 94 that is retained on an X-Y positioning stage 96. The sequence of FIG.4 can be coordinated with detector 18. Detector 18 further includes a fiber optic sensor 98 to sense the contents of the vials in combination with an analyzer 100. Analyzer 100 can utilize chromatography, infra red spectroscopy, mass spectroscopy, laser mass spectroscopy, microspectroscopy, NMR or the like to determine the constituency of each vial content.

In operation, X-Y positioning stage 96 of detector 18 positions an opening in array 94 directly beneath discharge port 52 so that when discharged, vial 24 falls cleanly into the array. Controller 16 registers the exact time a vial discharges from reactor vessel 14. X-Y positioning stage 96 moves array 94 beneath fiber optic sensor 98, which senses the contents of vial 24 for analysis by analyzer 100. For example, if the method and system of the invention is used to conduct a combinatorial synthesis to select a carbonylation catalyst and/or to determine optimum carbonylation reaction conditions, the analyzer analyzes the contents of the vial for carbonylated product. In this case, the analyzer can use Raman spectroscopy. The Raman peak is integrated using the analyzer electronics and the resulting data can be stored in the controller. Other analytical methods may be used as noted above.

The sequential combinatorial chemical synthesis herein described can be used with any suitable reactant system. For example, the system and method herein can be used for determining a method for producing diphenyl carbonate (DPC). Diphenyl carbonate (DPC) is useful, *inter alia*, as an intermediate in the preparation of polycarbonates. One method for producing DPC involves the carbonylation of a hydroxyaromatic compound (e.g., phenol) in the presence of a catalyst system. A carbonylation catalyst system typically includes a Group VIII B metal (e.g., palladium), a halide composition, and a combination of inorganic co-catalysts (IOCCs). This one step reaction is typically carried out in a continuous reactor at high temperature and pressure with gas sparging. Insufficient gas/liquid mixing can result in low yields of DPC. Generally, testing of new catalyst systems has been

accomplished at macro-scale and, because the mechanism of this carbonylation reaction is not fully understood, the identity of additional effective IOCCs has eluded practitioners. An embodiment of the present invention allows this homogeneous carbonylation reaction to be carried out in parallel with various potential catalyst systems and, consequently, this embodiment can be used to identify effective IOCCs for the carbonylation of phenol.

The following example is provided in order that those skilled in the art will be better able to understand and practice the present invention. This example is intended to serve as an illustration and not as a limitation of the present invention as defined in the claims herein.

Example

5

10

15

20

25

30

The economics of producing DPC by the above-mentioned carbonylation process is partially dependent on the number of moles of DPC produced per mole of Group VIII B metal utilized. In the following example, the Group VIII B metal utilized is palladium. For convenience, the number of moles of DPC produced per mole of palladium utilized is referred to as the palladium turnover number (Pd TON). Unless otherwise specified, all parts are by weight; all equivalents are relative to palladium; and all reactions are carried out in 2 ml glass vials at 90-100° C in a 10% O₂ in CO atmosphere at an operating pressure of 95-110 atm. Reaction is generally 2-3 hours. Reaction products are verified by gas chromatography.

This example illustrates an identification of an active and selective catalyst for the production of aromatic carbonates. The procedure identifies the best catalyst from a complex chemical space, where the chemical space is defined as an assemblage of all possible experimental conditions defined by a set of variable parameters such as formulation ingredient identity or amount or process parameter such as reaction time, temperature, or pressure. In the Example, an initial iteration examines an experimental formulation consisting of six chemical species shown in TABLE 1 and the process parameters shown in TABLE 2.

TABLE 1

	Formulation Type Parameter	Formulation Amount
	Variation	Parameter Variation
Precious metal catalyst	Held Constant	Held Constant
Metal Catalyst 1 (M1)	Fe, Cu,Ni,Pb,Re (as their	5, 20 (as molar ratios to
	acetylacetonates)	precious metal catalyst)
Metal Catalyst 2 (M2)	V, W, Ce,La,Sn (as their	5, 20 (as molar ratios to
	acetylacetonates)	precious metal catalyst)
Cosolvent (CS)	Dimethylformamide (DMFA),	Varied independently in
	Dimethylacetamide (DMAA),	amount. Values are 500,
	Tetrahydrofuran (THF),	4000 (as molar ratios to
	Diglyme (DiGly),	precious metal catalyst)
	Diethylacetamide (DEAA)	
Hydroxyaromatic	Held constant	Sufficient added to achieve
compound		constant sample volume

TABLE 2

Process Parameter	Process Parameter Variation					
Pressure	1000 psi, 1500 psi (8% Oxygen in Carbon Monoxide)					
Temperature	100 C, 120 C					
Reaction Time	1 hour, 2 hours .					

The size of the initial chemical space defined by the parameters of TABLE 1 and TABLE 2 is calculated as 8000 possibilities. This is a very large experiment for conventional techniques. In Iteration 1 of the process, a 400-sample subset of the 8000 possibilities is selected to screen formulation factors (M1, M2, and CS) while maintaining full representation of the quantity and process factors. A Latin Square design strategy is applied to generate a 5x5 square of the formulation factors. A Latin Square is an orthogonal design that allows each value of each factor to combine with each value of each other factor exactly once. In the present instance, the Latin Square is represented in abbreviated form in TABLE 3 and fully expanded in TABLE 4.

TABLE 3

M1

Fe Cu Ni Pb Re

W Ce

M2

V

5

10

DMFA	DMAA	THF	DiGly	DEAA
DMAA	THF	DiGly	DEAA	DMFA
THF	DiGly	DEAA	DMFA	DMAA

La Sn

DiGly	DEAA	DMFA	DMAA	THF
DEAA	DMFA	DMAA	THF	DiGly

TABLE 4

Ml1	Ml2	Cosolvent	TON
Cu	V	DMFA	2158
Cu	W	DMAA	2873
Cu	Ce	THF	1519
Cu	La	DiGly	1416
Cu	Sn	DEAA	1336
Fe	V	DMAA	3695
Fe	W	THF	4012
Fe	Ce	DiGly	2983
Fe	La	DEAA	2882
Fe	Sn	DMFA	3034
Ni	V	THF	347
Ni	W	DiGly	1122
Ni	Ce	DEAA	154
Ni	La .	DMFA	44
Ni	Sn	DMAA	252
Pb	V	DiGly	522
Pb	W	DEAA	1127
Pb	Ce	DMFA	102
Pb	La	DMAA	139
Pb	Sn	THF	49

Re	V	DEAA	492
Re	W	DMFA	1184
Re	Ce	DMAA	298
Re	La	THF	89
Re	Sn	DiGly	55

A 16-run 2-level fractional factorial design is generated in the six process variables. A 2-level fractional factorial design is an experiment with >1 adjustable control parameters (factors), each of which takes on 2 values (levels). All possible combinations of the factors and levels are generated. A fraction of the possible combinations is selected to maximize the value of information gained from the experiment. In this Example, six process variables generate 64 possibilities, of which one-fourth is selected according to the fractional factorial design. TABLE 5 shows the selected possibilities.

10			TABLE	5		
	M1 amt	M2 amp	CS amt	Pressure	Temp	Time
	5.00	20.00	500.00	1000.00	120.00	2.00
	20.00	5.00	500.00	1200.00	120.00	2.00
	5.00	5.00	500.00	1000.00	100.00	1.00
15	5.00	5.00	500.00	1200.00	100.00	2.00
	5.00	5.00	4000.00	1000.00	120.00	2.00
	5.00	20.00	500.00	1200.00	120.00	1.00
	5.00	20.00	4000.00	1200.00	100.00	2.00
	5.00	5.00	4000.00	1200.00	120.00	1.00
20	20.00	20.00	500.00	1200.00	100.00	1.00
	20.00	20.00	4000.00	1200.00	120.00	2.00
	20.00	5.00	4000.00	1000.00	100.00	2.00
	20.00	20.00	500.00	1000.00	100.00	2.00
	5.00	20.00	4000.00	1000.00	100.00	1.00
25	20.00	5.00	4000.00	1200.00	100.00	1.00
	20.00	20.00	4000.00	1000.00	120.00	1.00
	20.00	5.00	500.00	1000.00	120.00	1.00

A composite design is then generated in which each run of the fractional factorial design is performed at each combination of the Latin Square, for a total of 25x16 = 400 samples. The composite design is sorted by pressure, temperature and time as shown in TABLE 6.

					TABL	E 6			
Sample	M1	M2	CS	M1 am	t M2 am	t CS amt	Pressure	Temp	Time
1	Cu	V	DMFA	5	5	500	1000	100	1
2	Cu	V	DMFA	5	20	4000	1000	100	1
3	Cu	W	DMAA	5	5	500	1000	100	1
4	Cu	· W	DMAA	5	20	4000	1000	100	1
5	Cu	Се	THF	5	5	500	1000	100	1
6	Cu	Ce	THF	5	20	4000	1000	100	1
7	Cu	La	DiGly	5	5	500	1000	100	1
8	Cu	La	DiGly	5	20	4000	1000	100	1 ·
9	Cu	Sn	DEAA	5	5	500	1000	100	1
10	Cu	Sn	DEAA	5	20	4000	1000	100	1
11	Fe	V	DMAA	5	5	500	1000	100	1
12	Fe	V	DMAA	5	20	4000	1000	100	1
13	Fe	W	THF	5	5	500	1000	100	1
14	Fe	W	THF	5	20	4000	1000	100	1
15	Fe	Се	DiGly	5	5	500	1000	100	1

16	Fe	Се	DiGly	5	20	4000	1000	100	1
17	Fe	La	DEAA	5	5	500	1000	100	1
18	Fe	La	DEAA	5	20	4000	1000	100	1
19	Fe	Sn	DMFA	5	5	500	1000	100	1
20	Fe	Sn	DMFA	5	20	4000	1000	100	1
21	Ni	V	THF	5	5	500	1000	100	1
22	Ni	V	THF	5	20	4000	1000	100	1
23	Ni	W	DiGly	5	5	500	1000	100	1
24	Ni	W	DiGly	5	20	4000	1000	100	1
25	Ni	Ce	DEAA	5	5	500	1000	100	1
26	Ni	Се	DEAA	5	20	4000	1000	100	1
27	Ni	La	DMFA	5	5	500	1000	100	1
28	Ni	La	DMFA	5	20	4000	1000	100	1
29	Ni	Sn	DMAA	. 5	5	500	1000	100	1
30	Ni	Sn	DMAA	5	20	4000	1000	100	1
31	Pb	V	DiGly	5	5	500	1000	100	1
32	Pb	V	DiGly	5	20	4000	1000	100	1
33	Pb	W	DEAA	5	5	500	1000	100	1
34	Pb	W	DEAA	5	20	4000	1000	100	1
35	Pb	Се	DMFA	5	5	500	1000	100	1

36	Pb	Ce	DMFA	5	20	4000	1000	100	1
37	Pb	La	DMAA	5	5	500	1000	100	1
38	. Pb	La	DMAA	5	20	4000	1000	100	1
39	Pb	Sn	THF	5	5	500	1000	100	1
40	Pb	Sn	THF	5	20	4000	1000	100	1
41	Re	V	DEAA	5	5	500	1000	100	1
42	Re	V	DEAA	5	20	4000	1000	100	1
43	Re	w	DMFA	5	5	500	1000	100	1.
44	Re	W	DMFA	5	20	4000	1000	100	1
45	Re	Ce	DMAA	5	5	500	1000	100	1
46	Re	Ce	DMAA	5	20	4000	1000	100	1
47	Re	La	THF	5	5	500	1000	100	1
48	Re	La	THF	5	20	4000	1000	100	1
49	Re	Sn	DiGly	5	5	500	1000	100	1
50	Re	Sn	DiGly	5	20	4000	1000	100	1
51	Cu	V	DMFA	20	5	4000	1000	100	2
52	Cu	V	DMFA	20	20	500	1000	100	2
53	Cu	W	DMAA	20	5	4000	1000	100	2
54	Cu	W	DMAA	20	20	500	1000	100	2
55	Cu	Ce	THF	20	5	4000	1000	100	2

56	Cu	Ce	THF	20	20	500	1000	100	2
57	Cu	La	DiGly	20	5	4000	1000	100	2
58	Cu	La	DiGly	20	20	500	1000	100	2
59	Cu	Sn	DEAA	20	5	4000	1000	100	2
60	Cu	Sn	DEAA	20	20	500	1000	100	2
61	Fe	V	DMAA	20	5	4000	1000	100	2
62	Fe	V	DMAA	20	20	500	1000	100	2
63	Fe	W	THF	20	5	4000	1000	100	2
64	Fe	W	THF	20	20	500	1000	100	2
65	Fe	Ce	DiGly	20	5	4000	1000	100	2
66	Fe	Ce	DiGly	20	20	500	1000	100	2
67	Fe	La	DEAA	20	5	4000	1000	100	2
68	Fe	La	DEAA	20	20	500	1000	100	2
69	Fe	Sn	DMFA	20	5	4000	1000	100	2
70	Fe	Sn	DMFA	20	20	500	1000	100	2
71	Ni	V	THF	20	5	4000	1000	100	2
72	Ni	V	THF	20	20	500	1000	100	2
73	Ni	W	DiGly	20	5	4000	1000	100	2
74	Ni	w	DiGly	20	20	500	1000	100	2
75	Ni	Ce	DEAA	20	5	4000	1000	100	2

76	Ni	Ce	DEAA	20	20	500	1000	100	2
77	Ni	La	DMFA	20	5	4000	1000	100	2
78	Ni	La	DMFA	20	20	500	1000	100	2
79	Ni	Sn	DMAA	20	5	4000	1000	100	2
80	Ni	Sn	DMAA	20	20	500	1000	100	2
81	Pb	V	DiGly	20	5	4000	1000	100	2
82	Pb	V	DiGly	20	20	500	1000	100	2
83	Pb	W	DEAA	20	5	4000	1000	100	2
84	Pb	W	DEAA	20	20	500	1000	100	2
85	Pb	Ce	DMFA	20	5	4000	1000	100	2
86	Pb	Ce	DMFA	20	20	500	1000	100	2
87	Pb	La	DMAA	20	5	4000	1000	100	2
88	Pb	La	DMAA	20	20	500	1000	100	2
89	Pb	Sn	THF	20	5	4000	1000	100	2
90	Pb	Sn	THF	20	20	500	1000	100	2
91	Re	V	DEAA	20	5	4000	1000	100	2
92	Re	V	DEAA	20	20	500	1000	100	2
93	Re	W	DMFA	20	5	4000	1000	100	2
94	Re	w	DMFA	20	20	500	1000	100	2
95	Re	Ce	DMAA	20	5	4000	1000	100	2

96	Re	Ce	DMAA	20	20	500	1000	100	2
97	Re	La	THF	20	5	4000	1000	100	2
98	Re	La	THF	20	20	500	1000	100	2
99	Re	Sn	DiGly	20	5	4000	1000	100	2
100	Re	Sn	DiGly	20	20	500	1000	100	2
101	Cu	V	DMFA	20	20	4000	1000	120	1
102	Cu	V	DMFA	20	5	500	1000	120	1
103	Cu	W	DMAA	20	20	4000	1000	120	1
104	Cu	W	DMAA	20	5	500	1000	120	1
105	Cu	Ce	THF	20	20	4000	1000	120	1
106	Cu	Ce	THF	20	5	500	1000	120	1
107	Cu	La	DiGly	20	20	4000	1000	120	1
108	Cu	La	DiGly	20	5	500	1000	120	1
109	Cu	Sn	DEAA	20	20	4000	1000	120	1
110	Cu	Sn	DEAA	20	5	500	1000	120	1
111	Fe	V	DMAA	20	20	4000	1000	120	1
112	Fe	V	DMAA	20	5	500	1000	120	1
113	Fe	W	THF	20	20	4000	1000	120	1
114	Fe	w	THF	20	5	500	1000	120	1
115	Fe	Се	DiGly	20	20	4000	1000	120	1

116	Fe	Ce	DiGly	20	5	500	1000	120	1
117	Fe	La	DEAA	20	20	4000	1000	120	1
118	Fe	La	DEAA	20	5	500	1000	120	1
119	Fe	Sn	DMFA	20	20	4000	1000	120	1
120	Fe	Sn	DMFA	20	5	500	1000	120	1
121	Ni	V	THF	20	20	4000	1000	120	1
122	Ni	V	THF	20	5	500	1000	120	1
123	Ni	W	DiGly	20	20	4000	1000	120	1
124	Ni	W	DiGly	20	5	500	1000	120	1
125	Ni	Ce	DEAA	20	20	4000	1000	120	1
126	Ni	Ce	DEAA	20	5	500	1000	120	1
127	Ni	La	DMFA	20	20	4000	1000	120	1
128	Ni	La	DMFA	20	5	500	1000	120	1
129	Ni	Sn	DMAA	20	20	4000	1000	120	1
130	Ni	Sn	DMAA	20	5	500	1000	120	1
131	Pb	V	DiGly	20	20	4000	1000	120	1
132	Pb	V	DiGly	20	5	500	1000	120	1
133	Pb	W	DEAA	20	20	4000	1000	120	1
134	Pb	W	DEAA	20	5	500	1000	120	1
135	Pb	Ce	DMFA	20	20	4000	1000	120	1

136	Pb C	e DMFA	20	5	500	1000	120	1
137	Pb L	a DMAA	20	20	4000	1000	120	1
138	Pb L	a DMAA	20	5	500	1000	120	1
139	Pb Si	n THF	20	20	4000	1000	120	1
140	Pb Si	n THF	20	5	500	1000	120	1
141	Re V	DEAA	20	20	4000	1000	120	1
142	Re V	DEAA	20	5	500	1000	120	1
143	Re W	DMFA	20	20	4000	1000	120	1
144	Re W	DMFA	20	5	500	1000	120	1
145	Re C	e DMAA	20	20	4000	1000	120	1
146	Re Co	e DMAA	20	5	500	1000	120	1
147	Re La	a THF	20	20	4000	1000	120	1
148	Re La	a THF	20	5	500	1000	120	1
149	Re Sr	n DiGly	20	20	4000	1000	120	1
150	Re Sr	n DiGly	20	5	500	1000	120	1
151	Cu V	DMFA	5	20	500	1000	120	2
152	Cu V	DMFA	5	5	4000	1000	120	2
153	Cu W	DMAA	5	20	500	1000	120	2
154	Cu W	DMAA	5	5	4000	1000	120	2
155	Cu Ce	THF	5	20	500	1000	120	2

156	Cu	Ce	THF	5	5	4000	1000	120	2
157	Cu	La	DiGly	5	20	500	1000	120	2
158	Cu	La	DiGly	5	5	4000	1000	120	2
159	Cu	Sn	DEAA	5	20	500	1000	120	2
160	Cu	Sn	DEAA	5	5	4000	1000	120	2
161	Fe	V	DMAA	5	20	500	1000	120	2
162	Fe	V	DMAA	5	5	4000	1000	120	2
163	Fe	W	THF	5	20	500	1000	120	2
164	Fe	W	THF	-5	5	4000	1000	120	2
165	Fe	Ce	DiGly	5	20	500	1000	120	2
166	Fe	Ce	DiGly	5	5	4000	1000	120	2
167	Fe	La	DEAA	5	20	500	1000	120	2
168	Fe	La	DEAA	5	5	4000	1000	120	2
169	Fe	Sn	DMFA	5	20	500	1000	120	2
170	Fe	Sn	DMFA	5	5	4000	1000	120	2
171	Ni	V	THF	5	20	500	1000	120	2
172	Ni	v	THF	5	5	4000	1000	120	2
173	Ni	W	DiGly	5	20	500	1000	120	2
174	Ni	W	DiGly	5	5	4000	1000	120	2
175	Ni	Се	DEAA	5	20	500	1000	120	2

176	Ni	Ce	DEAA	5	5	4000	1000	120	2
177	Ni	La	DMFA	5	20	500	1000	120	2
178	Ni	La	DMFA	5	5	4000	1000	120	2
179	Ni	Sn	DMAA	5	20	500	1000	120	2
180	Ni	Sn	DMAA	5	5	4000	1000	120	2
181	Pb	V	DiGly	5	20	500	1000	120	2
182	Pb	V	DiGly	5	5	4000	1000	120	2
183	Pb	W	DEAA	5	20	500	1000	120	2
184	Pb	W	DEAA	5	5	4000	1000	120	2
185	Pb	Ce	DMFA	5	20	500	1000	120	2
186	Pb	Ce	DMFA	5	5	4000	1000	120	2
187	Pb	La	DMAA	5	20	500	1000	120	2
188	Pb	La	DMAA	5	5	4000	1000	120	2
189	Pb	Sn	THF	5	20	500	1000	120	2
190	Pb	Ŝn	THF	5	5	4000	1000	120	2
191	Re	V	DEAA	5	20	500	1000	120	2
192	Re	V	DEAA	5	5	4000	1000	120	2
193	Re	W	DMFA	5	20	500	1000	120	2
194	Re	W	DMFA	5	5	4000	1000	120	2
195	Re	Ce	DMAA	5	20	500	1000	120	2

196	Re Ce	DMAA	5	5	4000	1000	120	2
197	Re La	THF	5	20	500	1000	120	2
198	Re La	THF	5	5	4000	1000	120	2
199	Re Sn	DiGly	5	20	500	1000	120	2
200	Re Sn	DiGly	5	5	4000	1000	120	2
201	Cu V	DMFA	20	20	500	1200	100	1
202	Cu V	DMFA	20	5	4000	1200	100	1
203	Cu W	DMAA	20	20	500	1200	100	1
204	Cu W	DMAA	20	5	4000	1200	100	1
205	Cu Ce	THF	20	20	500	1200	100	1
206	Cu Ce	THF	20	5	4000	1200	100	1
207	Cu La	DiGly	20	20	500	1200	100	1
208	Cu La	DiGly	20	5	4000	1200	100	1
209	Cu Sn	DEAA	20	20	500	1200	100	1
210	Cu Sn	DEAA	20	5	4000	1200	100	1
211	Fe V	DMAA	20	20	500	1200	100	1
212	Fe V	DMAA	20	5	4000	1200	100	1
213	Fe W	THF	20	20	500	1200	100	1
214	Fe W	THF	20	5	4000	1200	100	1
215	Fe Ce	DiGly	20	20	500	1200	100	1

216	Fe	Ce	DiGly	20	5	4000	1200	100	1
217	Fe	La	DEAA	20	20	500	1200	100	1
218	Fe	La	DEAA	20	5	4000	1200	100	1
219	Fe	Sn	DMFA	20	20	500	1200	100	1
220	Fe	Sn	DMFA	20	5	4000	1200	100	1
221	Ni	V	THF	20	20	500	1200	100	1
222	Ni	V	THF	20	5	4000	1200	100	1
223	Ni	W	DiGly	20	20	500	1200	100	1
224	Ni	W	DiGly	20	5	4000	1200	100	1
225	Ni	Ce	DEAA	20	20	500	1200	100	1
226	Ni	Ce	DEAA	20	5	4000	1200	100	1
227	Ni	La	DMFA	20	20	500	1200	100	1
228	Ni	La	DMFA	20	5	4000	1200	100	1
229	Ni	Sn	DMAA	20	20	500	1200	100	1
230	Ni	Sn	DMAA	20	5	4000	1200	100	1
231	Pb	v	DiGly	20	20	500	1200	100	1
232	Pb	V	DiGly	20	5	4000	1200	100	1
233	Pb	W	DEAA	20	20	500	1200	100	1
234	Pb	w	DEAA	20	5	4000	1200	100	1
235	Pb	Се	DMFA	20	20	500	1200	100	1

236	Pb	Ce	DMFA	20	5	4000	1200	100	1
237	Pb	La	DMAA	20	20	500	1200	100	1
238	Pb	La	DMAA	20	5	4000	1200	100	1
239	Pb	Sn	THF	20 ·	20	500	1200	100	1
240	Pb	Sn	THF	20	5	4000	1200	100	1
241	Re	V	DEAA	20	20	500	1200	100	1
242	Re	V	DEAA	20	5	4000	1200	100	1
243	Re	W	DMFA	20	20	500	1200	100	1
244	Re	W	DMFA	20	5	4000	1200	100	1
245	Re	Ce	DMAA	20	20	500	1200	100	1
246	Re	Ce	DMAA	20	5	4000	1200	100	1
247	Re	La	THF	20	20	500	1200	100	1
248	Re	La	THF	20	5	4000	1200	100	1.
249	Re	Sn	DiGly	20	20	500	1200	100	1
250	Re	Sn	DiGly	20	5	4000	1200	100	1
251	Cu	V	DMFA	5	5	500	1200	100	2
252	Cu	V	DMFA	5	20	4000	1200	100	2
253	Cu	W	DMAA	5	5	500	1200	100	2
254	Cu	w	DMAA	5	20	4000	1200	100	2
255	Cu	Ce	THF	5	5	500	1200	100	2

256	Cı	ı Ce	THF	5	20	4000	1200	100	2
257	Cı	ı La	DiGly	5	5	500	1200	100	2
258	Cı	ı La	DiGly	5	20	4000	1200	100	2
259	Cı	ı Sn	DEAA	5	5	500	1200	100	2
260	Cu	ı Sn	DEAA	5	20	4000	1200	100	2
261	·Fe	V	DMAA	5	5	500	1200	100	2
262	Fe	V	DMAA	5	20	4000	1200	100	2
263	Fe	W	THF	5	5	500	1200	100	2
264	Fe	W	THF	5	20	4000	1200	100	2
265	Fe	Ce	DiGly	5	5	500	1200	100	2
266	Fe	Ce	DiGly	5 .	20	4000	1200	100	2
267	Fe	La	DEAA	5	5	500	1200	100	2
268	Fe	La	DEAA	5	20	4000	1200	100	2
269	Fe	Sn	DMFA	5	5	500	1200	100	2
270	Fe	Sn	DMFA	5	20	4000	1200	100	2
271	Ni	V	THF	5	5	500	1200	100	2
272	Ni	V	THF	5	20	4000	1200	100	2
273	Ni	W	DiGly	5	5	500	1200	100	2
274	Ni	W	DiGly	5	20	4000	1200	100	2
275	Ni	Ce	DEAA	5	5	500	1200	100	2

2	276	Ni	Ce	DEAA	5	20	4000	1200	100	2
2	277	Ni	La	DMFA	5	5	500	1200	100	2
2	278	Ni	La	DMFA	5	20	4000	1200	100	2
2	279	Ni	Sn	DMAA	5	5	500	1200	100	2
2	280	Ni	Sn	DMAA	5	20	4000	1200	100	2
2	281	Pb	V	DiGly	5	5	500	1200	100	2
2	282	Pb	V	DiGly	5	20	4000	1200	100	2
2	283	Pb	Ŵ	DEAA	5	5	500	1200	100	2
2	284	Pb	W	DEAA	5	20	4000	1200	100	2
2	285	Pb	Ce	DMFA	5	5	500	1200	100	2
2	286	Pb	Ce	DMFA	5	20	4000	1200	100	2
2	287	Pb	La	DMAA	5	5	500	1200	100	2
2	288	Pb	La	DMAA	5	20	4000	1200	100	2
2	289	Pb	Sn	THF	5	5	500	1200	100	2
2	290	Pb	Sn	THF	5	20	4000	1200	100	2
2	.91	Re	V	DEAA	5	5	500	1200	100	2
2	292	Re	V	DEAA	5	20	4000	1200	100	2
2	293	Re	W	DMFA	5	5	500	1200	100	2
2	294	Re	W	DMFA	5	20	4000	1200	100	2
2	.95	Re	Ce	DMAA	5	5	500	1200	100	2

296	Re	Ce	DMAA	5	20	4000	1200	100	2
297	Re	La	THF	5	5	500	1200	100	2
298	Re	La	THF	5	20	4000	1200	100	2
299	Re	Sn	DiGly	5	5	500	1200	100	2
300	Re	Sn	DiGly	5	20	4000	1200	100	2
301	Cu	V	DMFA	5	20	500	1200	120	1
302	Cu	V	DMFA	5	5	4000	1200	120	1
303	Cu	W	DMAA	5	20	500	1200	120	1
304	Cu	W	DMAA	5	5	4000	1200	120	1
305	Cu	Ce	THF	5	20	500	1200	120	1
306	Cu	Ce	THF	5	5	4000	1200	120	1
307	Cu	La	DiGly	5	20	500	1200	120	1
308	Cu	La	DiGly	5	5	4000	1200	120	1
309	Cu	Sn	DEAA	5	20	500	1200	120	1
310	Cu	Sn	DEAA	5	5	4000	1200	120	1
311	Fe	V	DMAA	5	20	500	1200	120	1
312	Fe	V	DMAA	5	5	4000	1200	120	1
313	Fe	W	THF	5	20	500	1200	120	1
314	Fe	W	THF	5	5	4000	1200	120	1
315	Fe	Ce	DiGly	5	20	500	1200	120	1

316	Fe	Ce	DiGly	5	5	4000	1200	120	1
317	Fe	La	DEAA	5	20	500	1200	120	1
318	Fe	La	DEAA	5	5	4000	1200	120	1
319	Fe	Sn	DMFA	5	20	500	1200	120	1
320	Fe	Sn	DMFA	5	5	4000	1200	120	1
321	Ni	V	THF	5	20	500	1200	120	1
322	Ni	V	THF	5	5	4000	1200	120	1
323	Ni	W	DiGly	5	20	500	1200	120	1
324	Ni	W	DiGly	5	5	4000	1200	120	1
325	Ni	Се	DEAA	5	20	500	1200	120	1
326	Ni	Ce	DEAA	5	5 .	4000	1200	120	1
327	Ni	La	DMFA	5	20	500	1200	120	1
328	Ni	La	DMFA	5	5	4000	1200	120	1
329	Ni	Sn	DMAA	5	20	500	1200	120	1
330	Ni	Sn	DMAA	5	5	4000	1200	120	- 1
331	Pb	V	DiGly	5	20	500	1200	120	1
332	Pb	V	DiGly	5	5	4000	1200	120	1
333	Pb	W	DEAA	5	20	500	1200	120	1
334	Pb	w	DEAA	5	5	4000	1200	120	1
335	Pb	Ce	DMFA	5	20	500	1200	120	1

336	Pb	Ce	DMFA	5	5	4000	1200	120	1
337	Pb	La	DMAA	. 5	20	500	1200	120	1
338	Pb	La	DMAA	. 5	5	4000	1200	120	1
339	Pb	Sn	THF	5	20	500	1200	120	1
340	Pb	Sn	THF	5	5	4000	1200	120	1
341	Re	V	DEAA	5	20	500	1200	120	1
. 342	Re	V	DEAA	5	5	4000	1200	120	1
343	Re	W	DMFA	5	20	500	1200	120	1
344	Re	W	DMFA	5	5	4000	1200	120	1
345	Re	Ce	DMAA	5	20	500	1200	120	1
346	Re	Ce	DMAA	5	5	4000	1200	120	1
347	Re	La	THF	5	20	500	1200	120	1
348	Re	La	THF	5	5	4000	1200	120	1
349	Re	Sn	DiGly	5	20	500	1200	120	1
350	Re	Sn	DiGly	5	5	4000	1200	120	1
351	Cu	V	DMFA	20	5	500	1200	120	2
352	Cu	V	DMFA	20	20	4000	1200	120	2
353	Cu	w	DMAA	20	5	500	1200	120	2
354	Cu	W	DMAA	20	20	4000	1200	120	2
355	Cu	Ce	THF	20	5	500	1200	120	2

356	Cu	Ce	THF	20	20	4000	1200	120	2
357	Cu	La	DiGly	20	5	500	1200	120	2
358	Cu	La	DiGly	20	20	4000	1200	120	2
359	Cu	Sn	DEAA	20	5	500	1200	120	2
360	Cu	Sn	DEAA	20	20	4000	1200	120	2
361	Fe	V	DMAA	20	5	500	1200	120	2
362	Fe	V	DMAA	20	20	4000	1200	120	2
363	Fe	W	THF	20	5	500	1200	120	2
364	Fe	W	THF	20	20	4000	1200	120	2
365	Fe	Ce	DiGly	20	5	500	1200	120	2
366	Fe	Ce	DiGly	20	20	4000	1200	120	2
367	Fe	La	DEAA	20	5	500	1200	120	2
368	Fe	La	DEAA	20	20	4000	1200	120	2
369	Fe	Sn	DMFA	20	5	500	1200	120	2
370	Fe	Sn	DMFA	20	20	4000	1200	120	2
371	Ni	V	THF	20	5	500	1200	120	2
372	Ni	V	THF	20	20	4000	1200	120	2
373	Ni	w	DiGly	20	5	500	1200	120	2
374	Ni	W	DiGly	20	20	4000	1200	120	2
375	Ni	Се	DEAA	20	5	500	1200	120	2

376	Ni	Ce	DEAA	20	20	4000	1200	120	2
377	Ni	La	DMFA	20	5	500	1200	120	2
378	Ni	La	DMFA	20	20	4000	1200	120	2
379	Ni	Sn	DMAA	20	5	500	1200	120	2
380	Ni	Sn	DMAA	20	20	4000	1200	120	2
381	Pb	V	DiGly	20	5	500	1200	120	2
382	Pb	V	DiGly	20	20	4000	1200	120	2
383	Pb	W	DEAA	20	5	500	1200	120	2
384	Pb	W	DEAA	20	20	4000	1200	120	2
385	Pb	Ce	DMFA	20	5	500	1200	120	2
386	Pb	Се	DMFA	20	20	4000	1200	120	2
387	Pb	La	DMAA	20	5	500	1200	120	2
388	Pb	La	DMAA	20	20	4000	1200	120	2
389	Pb	Sn	THF	20	5	500	1200	120	2
390	Pb	Sn	THF	20	20	4000	1200	120	2
391	Re	V	DEAA	20	5	500	1200	120	2
392	Re	V	DEAA	20	20	4000	1200	120	2
393	Re	w	DMFA	20	5	500	1200	120	2
394	Re	w	DMFA	20	20	4000	1200	120	2
395	Re	Се	DMAA	20	5	500	1200	120	2

10

396	Re	Ce	DMAA	20	20	4000	1200	120	2
397	Re	La	THF	20	5	500	1200	120	2
398	Re	La	THF	20	20	4000	1200	120	2
399	Re	Sn	DiGly	20	5	500	1200	120	2
400	Re	Sn	DiGly	20	20	4000	1200	120	2

In this evaluation, each of the metal acetylacetonates, the DMAA, and the DMFA is made up as a stock solution in phenol. An appropriate quantity of each stock solution is then combined using a Hamilton MicroLab 4000 laboratory robot into a single vial for mixing. For example, the stock solutions to produce vials 1, 65, 129,193, 257, 321, 385, and 449, are 0.01 molar Pd(acetylacetonate), 0.01 molar each of Fe(acetylacetonate) and V(acetylacetonate) and 5 molar DMFA. Ten ml of each stock solution is produced by manual weighing and mixing. Aliquots of the stock solutions are measured as follows in TABLE 7. The mixture is stirred using a miniature magnetic stirrer, and then 25 microliters are measured out to each of eight 2-ml vials using the Hamilton robot. This small quantity forms a thin film on the vial bottom.

TABLE 7

25 microliters
125 microliters
125 microliters
25 microliters
700 microliters

10

After each mixture is made, mixed, and distributed to 2-ml vials, the vials are capped using "star" caps (which allow gas exchange with the environment) and placed in the loader of FIG.1. The tubular reactor system is heated and pressurized to the conditions shown as Block 1 in TABLE 8 and the automatic loading and processing procedure discussed above is begun. Loading and unloading times are controlled so that each vial is in the heated reaction zone for the time shown in Block 1: 1 hour. The reaction zone can accommodate a stack of 20 vials. A new vial is added every three minutes until the stack is full, then one vial is removed and another added every three minutes thereafter. As vials progress down the stack, their exposure time is 20 x 3 minutes = 60 minutes = 1 hour.

TABLE 8

Block	Pressure (psi)	Temperature (°C)	Time (hours)
1	1000	100	1
2	1000	100	2
3	1000	120	1
4	1000	120	2
5	1200	100	1
6	1200	100 ·	2
7	1200	120	1
8	1200	120	2

As each vial exits the reactor, it falls into a new array and is analyzed by gasliquid chromatography.

Performance is expressed numerically as a catalyst turnover number or TON.

TON is defined as the number of moles of aromatic carbonate produced per mole of Palladium catalyst charged.

When all rows with the same pressure, temperature and reaction time have been processed, the pressure and temperature are adjusted to new conditions. The timing is adjusted and a next row is processed. This iteration is repeated until all conditions have been run. The performance of each vial is given in the column "TON" of TABLE 4. The TON's of TABLE 4 are averaged by each formulation component to give the results shown in TABLE 9. TAB:LE 9 shows that average TON is significantly larger for M1 = Fe or Cu; M2= V or W; and cosolvent = DMFA or DMAA. These are selected for a second iteration.

		TABLE 9							
M1	Mlave	M2	M2ave	Cosolvent	CS ave				
Cu	1860.3	V	1442.8	DMFA	1304.4				
Fe	3321.5	W	2063.5	DMAA	1451.5				
Ni	383.8	Ce	1011.2	THF	1203.1				
Pb	387.7	La	914.1	DiGly	1219.5				
Re	423.7	Sn	945.3	DEAA	11984				

10

5

In the second iteration of the process, experimental formulations consist of six chemical species shown in TABLE 10. Process parameters are shown in TABLE 11.

TABLE 10

	Formulation Type	Formulation Amount
	Parameter Variation	Parameter Variation
Precious metal catalyst	Held Constant	Held Constant
Metal Catalyst 1 (M1)	Fe or Cu (as their acetylacetonates)	5,20 (as molar ratios to precious metal catalyst)
Metal Catalyst 2 (M2)	V or W (as their acetylacetonates)	5,20 (as molar ratios to precious metal catalyst)
Cosolvent (CS)	Dimethylformamide	Varied independently in

10

15

	(DMFA) or	amount. Possible values
	Dimethylacetamide	were 500, 4000 (as molar
	(DMAA)	ratios to precious metal
		catalyst)
Hydroxyaromatic	Held constant	Sufficient added to achieve
compound		constant sample volume

TABLE 11

Process Parameter	Process Parameter Variation
Pressure	1000 psi, 1500 psi (8% Oxygen in Carbon Monoxide)
Temperature	100 C, 120 C
Reaction Time	1 hour, 2 hours

Size of an initial chemical space defined by the parameters of TABLE 10 and TABLE 11 is calculated as 512 possibilities. The 512 possibilities are organized into an experiment of the type known as a "full factorial design" with pressure, temperature, and reaction time parameters "blocked." A full factorial design is an experiment with >1 adjustable control parameters (factors) each of which can take on >1 value (levels). In a full factorial design experiment, an observation is taken at each of all possible combinations of levels that can be formed from the different factors. A full factorial design is capable of estimating all possible effects of the factors, including main effects and all interactions. The design is necessary where the intention of an experiment is to determine if there are unusual interactions, particularly between process and formulation variables. Where factors are "blocked," factors that are relatively difficult to quickly vary are grouped together. A full factorial design for the chemical space of this Example is shown in TABLE 12.

Block	M1	M1 amt	M2	M2 amt	cs	CS amt	Pressure	Temperature	Time	TON
1	Fe	5	V	5	DMFA	500	1000	100	1	1693.92
1	Cu	5	V	5	DMFA	500	1000	100 -	1	4091.21
1	Fe	20	V	5	DMFA	500	1000	100	1	1845.361
1	Cu	20	V	5	DMFA	500	1000	100	1	4038.68
1	Fe	5	W	5	DMFA	500	1000	100	1	1754.727
1	Cu	5	W	5	DMFA	500	1000	100	1	3956.726
1	Fe Cu	20 20	W W	5 5	DMFA DMFA	500 500	1000 1000	100 100	1	1903.599
1	Fe	5	V	20	DMFA	500	1000	100	1	3676.381 2237.44
1	Cu ·	5	v	20	DMFA	500	1000	100	1	4171.727
1	Fe	20	v	20	DMFA	500	1000	100	1	2665.677
1	Cu	20	V	20	DMFA	500	1000	100	1	4063.274
1	Fe	5	W	20	DMFA	500	1000 -	. 100	1	1741.315
1	Cu	5	W	20	DMFA	500	1000	100	1	4263.502
1	Fe	20	W	20	DMFA	500	1000	100	1	2264.471
1	Cu	20	W	20	DMFA	500	1000	100	1	3990.751
1	Fø Cu	5	V V	5	DMAA	500	1000	100	1	1862.09
1 1	Fe	5 20	v ·	5 5	DMAA DMAA	500 500	1000 1000	100 100	1	4000.029 1905.142
1	Cu	20	v	5	DMAA	500	1000	100	i	4195.94
1	Fe	5	w	5	DMAA	500	1000	100	1	2160.141
1	Cu	5	w	5	DMAA	500	1000	100	1	4556.547
1	Fe	20	W	5	DMAA	500	1000	100	1	2219.635
1	Cu	20	W	5	DMAA	500	1000	100	1	3939.92
1	Fe	5	V	20	DMAA	500	1000	100	1	2084.011
1	Cu	5	V	20	DMAA	500	1000	100	1	4214.699
1 .	Fe	20	V	20	DMAA	500	1000	100	1	2043.003
1	: Ću	20	V	20	DMAA	500	1000	100	1	3939.684
1	Fe Cu	5 5	W W	20 20	DMAA DMAA	500 500	1000	100	1	1659.084
1	Fe	20	W	20	DMAA	500 500	1000 1000	100 100	1	3834.039 1840.703
i	Cu	20	w	20	DMAA	500	1000	100	1	4183.744
1	Fe	5	v	5 '	DMFA	4000	1000	100	1	4451.489
1	Cu	5	V	5	DMFA	4000	1000	100	1	2199.05
	_									
1	Fe	20	V	5	DMFA	4000	1000	100	1	4345.231
1	Cu	20	V	5	DMFA	4000	1000	100	1	2177.339
1	Fe Cu	5 5	W W	5 5	DMFA DMFA	4000 4000	1000 1000	100 - 100	1 1	4439.784 1915.281
1	Fe	20	w	5	DMFA	4000	1000	100	1	3416.777
i	Cu	20	w	5	DMFA	4000	1000	100	1	1906.395
1	Fe	5	V	20	DMFA	4000	1000	100	1	3955.658
1	Cu	5	V	20	DMFA	4000	1000	100	1	2068.799
1	Fe	20	V	20	DMFA	4000	1000	100	1	3757.099
1	Cu	20	V	20	DMFA	4000	1000	100	1	2195.421
1	Fe	5	W	20	DMFA	4000	1000	100	1	4265.04
1	Cu	5	W	20	DMFA	4000	1000	100	1	2622.194
1 1	Fe Cu	20 20	W W	20 20	DMFA DMFA	4000 4000	1000 1000 :	100 - 100	1	4080.135
1	Fe	20 5	ν ν ∨	20 5	DMAA	4000 4000	1000 :	100	1 1	2165.103 3917.162
1	Cu	5	v	5	DMAA	4000	1000	100	1	2401.285
1	Fe	20	v	5	DMAA	4000	1000	100	i	3756.023
1	Cu	20	V	5	DMAA	4000	1000	100	1	1860.372
1	Fe	5	w	5	DMAA	4000	1000	100	1	3812.629
1	Cu	5	W	5	DMAA	4000	1000	100	1	1539.843
1	Fe	20	W	5	DMAA	4000	1000	100	1	4062.504
1	Cu	20	W	5	DMAA	4000	1000	100	1	2322.649
1	Fe	5	V	20	DMAA	4000	1000	100	1	4085.449
1	Cu Fe	5 20	V V	20 20	DMAA	4000	1000	100	1	1662.921
1	Cu	20 20	v	20 20	DMAA DMAA	4000 4000	1000 1000	100 100	1 1	4030.069 2271.779
1	Fe	5	w	20	DMAA	4000	1000	100	1	4267.062
. i	Cn .	5	w	20	DMAA	4000	1000	100	1	2020.112
i	Fe	20	w	20	DMAA	4000	1000	100	i	4066.339
1	Cu	20	W	20	DMAA	4000	1000	100	1	1900.791
2	Fe	5	٧	5	DMFA	500	1000	100	2	3700.711
2	Cu	5	٧	5	DMFA	500	1000	100	2	5105.03
. 2	Fe	20	٧	5 ,	DMFA	500	1000	100	2	3043.119
2	Cu	20	V	5	DMFA	500	1000	100	2	4908.279
2	Fe	5	W	5	DMFA	500	1000	100	2	2899.673

2										
~	Cu	5	W	5	DMFA	500	1000	100	2	4806.417
2	Fe	20	W	5	DMFA	500	1000	100	2	3321.028
2	Cu	20	W	5	DMFA	500	1000	100	2	5529.844
2	Fe	5	V	20	DMFA	500	1000	100	2	3145.139
2	Cu	5	v	20	DMFA	500	1000	100	2	5495.893
2	Fe	20	v	20	DMFA	500	1000	100	2	2599.752
2	Cu	20	v			500		100	2	4521,231
				20	DMFA		1000			
2	Fe	5	W	20	DMFA	500	1000	100	2	3139.919
2	Cu	5	W	20	DMFA	500	1000	100	2	5106.096
2	Fe	20	W	20	DMFA	500	1000	100	2	3252.493
2	Cu	20	W	20	DMFA	500	1000	100	2	5025.739
2	Fe	5	٧	5	DMAA	500	1000	100	2	2801.16
2	Cu	5	V	5	DMAA	500	1000	100	2	5625.641
2	Fe	20	V	5	DMAA	500	1000	s. 100	2	2995.132
2	Cu	20	v	5	DMAA	500	1000	100	2	4854.658
2	Fe	5	w	5	DMAA	500	1000	100	2	2743.656
2	Cu	5	w	5	DMAA	500	1000	100	2	4617.833
2	Fe	20	w	5	DMAA	500	1000	100	2	3023.491
2	Cu	20	W	5	DMAA	500	1000	100	2	5087.621
2	Fe	5	V	20	DMAA	500	1000	100 ′	2	3259.962
2	Cu	5	V	20	DMAA	500	1000	100	2	5375.063
2	Fe	20	٧	20	DMAA	500	1000	100	2	2816.106
2	Cu	20	V	20	DMAA	500	1000	100	2	4596.62
2	Fe	5	W	20	DMAA	500	1000	100	2	3301.399
2	Cu	5	W	20	DMAA	500	1000	100	2	5095.495
2	Fe	20	w	20	DMAA	500	1000	100	2	3062.839
2	Cu	20	w	20	DMAA	500	1000	100	2	4980.406
2	Fe	5	Ÿ	5	DMFA	4000	1000	100	2	5301.676
2	Cu	5	v	5	DMFA	4000		100		
							1000		2	2992.894
2	Fe	20	V	5	DMFA	4000	1000	100	2	5226.527
2	Cu	20	V	5	DMFA	4000	1000	100	2	3229.047
2	Fe	5	W	5	DMFA	4000	1000	100	2	4741.478
2	Cu	5	W	5	DMFA	4000	1000	100	2	3150.125
2	Fe	20	W	5	DMFA	4000	1000	100	2	4602.754
2	Cu	20	W	5	DMFA	4000	1000	100	2	2719.743
_	_	_							_	
2	Fe	5	V	20	DMFA	4000	1000	100	2	5004.734
2	Cu	5	V	20	DMFA	4000	1000	100	2	3115.677
2	Fe	20	V	20	DMFA	4000	1000	100	. 2	4969.642
2						4000	1000	100	2	
^	Cu	20	V	20	DMFA					2806.752
2	Cu Fe	20 5	V W	20 20	DMFA DMFA	4000	1000	100	2	4879.942
2								100 100		
2	Fe	5	W	20 20	DMFA DMFA	4000	1000		2 2	4879.942
2 2	Fe Cu Fe	5 5 20	w w	20 20 20	DMFA DMFA DMFA	4000 4000 4000	1000 1000 1000	100 100	2 2 2	4879.942 2891.03 4912.866
2 2 2	Fe Cu Fe Cu	5 5 20 20	w w w	20 20 20 20	DMFA DMFA DMFA DMFA	4000 4000 4000 4000	1000 1000 1000 1000	100 100 100	2 2 2 2	4879.942 2891.03 4912.866 3036.185
2 2 2 2	Fe Cu Fe Cu Fe	5 5 20 20 5	W W W V	20 20 20 20 5	DMFA DMFA DMFA DMFA DMAA	4000 4000 4000 4000 4000	1000 1000 1000 1000 1000	100 100 100 100	2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605
2 2 2 2 2	Fe Cu Fe Cu Fe Cu	5 5 20 20 5 5	W W W V	20 20 20 20 20 5	DMFA DMFA DMFA DMFA DMAA DMAA	4000 4000 4000 4000 4000 4000	1000 1000 1000 1000 1000 1000	100 100 100 100 100	2 2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5
2 2 2 2 2 2	Fe Cu Fe Cu Fe Cu	5 5 20 20 5 5 5	* * * * * * * * * * * * * * * * * * *	20 20 20 20 5 5	DMFA DMFA DMFA DMFA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000	1000 1000 1000 1000 1000 1000	100 100 100 100 100 100	2 2 2 2 2 2 . 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313
2 2 2 2 2 2 2 2	Fe Cu Fe Cu Fe Cu	5 5 20 20 5 5 20	w w w v v	20 20 20 20 5 5 5	DMFA DMFA DMFA DMFA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000	100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502
2 2 2 2 2 2 2 2 2	Fe Cu Fe Cu Fe Cu Fe Cu Fe	5 5 20 20 5 5 20 20	w w v v	20 20 20 20 5 5 5 5	DMFA DMFA DMFA DMAA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449
2 2 2 2 2 2 2 2 2 2 2	Fe Cu Fe Cu Fe Cu Fe Cu	5 5 20 20 5 5 20 20 5	w w v v v	20 20 20 20 5 5 5 5 5	DMFA DMFA DMFA DMAA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Fe Cu Fe Cu Fe Cu Fe Cu Fe	5 5 20 20 5 5 20 20 5 5	<pre>% % % > > > > </pre>	20 20 20 20 5 5 5 5 5 5	DMFA DMFA DMFA DMAA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Fe Cu e Cu e Cu e Cu e Cu e Cu	5 5 20 20 5 5 20 20 5 5 20 20	* * * * * * * * * * * * * * * * * * *	20 20 20 20 5 5 5 5 5 5 5	DMFA DMFA DMFA DMAA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe	5 5 20 20 5 5 20 20 5 5 20 20 5	* * * * * * * * * * * * * * * * * * *	20 20 20 5 5 5 5 5 5 5 5	DMFA DMFA DMFA DMAA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891 4690.863
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Fe Cu e Cu e Cu e Cu e Cu e Cu	5 5 20 20 5 5 20 20 5 5 20 20	* * * * * * * * * * * * * * * * * * *	20 20 20 20 5 5 5 5 5 5 5	DMFA DMFA DMFA DMAA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe	5 5 20 20 5 5 20 20 5 5 20 20 5	* * * * * * * * * * * * * * * * * * *	20 20 20 5 5 5 5 5 5 5 5	DMFA DMFA DMFA DMAA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891 4690.863
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Fe U e U e C Fe C F	5 5 20 20 5 5 20 20 5 5 20 20 5 5	W W W V V V W W W V V V V V V V V V V V	20 20 20 20 5 5 5 5 5 5 5 5 5 20 20	DMFA DMFA DMFA DMAA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891 4690.863 2695.653
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Fe Cu e Cu	5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20	W W W V V W W W V V V V V V V V V V V V	20 20 20 5 5 5 5 5 5 5 5 5 20 20 20	DMFA DMFA DMFA DMAA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891 4690.863 2695.653 5029.318 2964.375
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Fe U e U e U e U e U e U e U e U e FC	5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5	W W W V V V W W W V V V V W W W W W W W	20 20 20 5 5 5 5 5 5 5 5 20 20 20 20	DMFA DMFA DMFA DMFA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891 4690.863 2695.653 5029.318 2964.375 4540.673
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Fe U e U e U e U e C F C U e U e C F C F C F C F C F C F C F C F C F C	5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5	W W V V V V V V V V V V W W W W W W W W	20 20 20 5 5 5 5 5 5 5 5 20 20 20 20	DMFA DMFA DMFA DMFA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891 4690.863 2695.653 5029.318 2964.375 4540.673 2848.039
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Fe U e U e U e U e U e C Fe U e U e Fe U e C Fe C F	5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5	W W W V V V W W W W W W W W W W W W W W	20 20 20 5 5 5 5 5 5 5 5 20 20 20 20 20 20	DMFA DMFA DMFA DMFA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891 4690.863 2695.653 5029.318 2964.375 4540.673 2848.039 4994.425
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Fe u e u e u e u e u e u e u e u e cre cre cre cre cre cre cre cre cre c	5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 20 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	W W W V V V W W W W W W W W W W W W W W	20 20 20 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20	DMFA DMFA DMFA DMFA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891 4690.863 2695.653 5029.318 2964.375 4540.673 2848.039 4994.425 3097.556
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 3	Fe u e u e u e u e u e u e u e u e u e u	5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 5 5 5 5	W W W V V V W W W V V V W W W V V V V W W W V V V V W W W V V V V W W W V V V V W W W V V V V V W W W V V V V V W W W V V V V W W W V V V V V W W W V V V V V W W W V V V V V W W W V V V V V W W W V V V V V V W W W V V V V V V V W W W V V V V V V V V V V W W W V	20 20 20 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20	DMFA DMFA DMFA DMFA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 1	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891 4690.863 2695.653 5029.318 2964.375 4540.673 2848.039 4994.425 3097.556 3096.222
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 3 3	Fe u e u e u e u e u e u e u e u e u e u	5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 5	W W W V V V W W W W V V V V W W W V V V V V W W W V V V V V V W W W V	20 20 20 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 5 5	DMFA DMFA DMFA DMFA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2695.653 5029.318 2964.375 4540.673 2848.039 4994.425 3097.556 3096.222 1130.108
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 3 3 3	Fe U e U e U e U e U e U e U e U e U e U	5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 5	W W W V V V W W W V V V V V V V V V V V	20 20 20 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 5 5	DMFA DMFA DMFA DMFA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 1 1 1 1	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891 4690.863 2695.653 5029.318 2964.375 4540.673 2848.039 4994.425 3097.556 3096.222 1130.108 3223.721
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 3 3 3 3	Fe U e U e U e U e U e U e U e U e U e U	5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	W W W V V V W W W V V V V V V V V V V V	20 20 20 5 5 5 5 5 5 5 5 20 20 20 20 20 20 5 5 5 5	DMFA DMFA DMFA DMFA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 1 1 1 1 1	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891 4690.863 2695.653 5029.318 2964.375 4540.673 2848.039 4994.425 3097.556 3096.222 1130.108 3223.721 1391.525
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 3 3 3 3	Fe u e u e u e u e u e u e u e u e u e u	5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 5	W W W V V V W W W V V V W W W W V V V W W W W W V V V W W W W V V V W	20 20 20 5 5 5 5 5 5 5 5 20 20 20 20 20 5 5 5 5	DMFA DMFA DMFA DMFA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891 4690.863 2695.653 5029.318 2964.375 4540.673 2848.039 4994.425 3097.556 3096.222 1130.108 3223.721 1391.525 3367.514
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 3 3 3 3	Fe u e u e u e u e u e u e u e u e u e u	5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 5	W W W V V V W W W V V V V W W W W W W W	20 20 20 5 5 5 5 5 5 5 5 20 20 20 20 20 5 5 5 5	DMFA DMFA DMFA DMFA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 1 1 1 1 1 1	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891 4690.863 2695.653 5029.318 2964.375 4540.673 2848.039 4994.425 3097.556 3096.222 1130.108 3223.721 1391.525 3367.514 735.8303
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 3 3 3 3	Fe U e U e U e U e U e U e U e U e C F C F C F C F C F C F C F C F C F C	5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 5	W W W V V V V W W W V V V V W W W W W W	20 20 20 5 5 5 5 5 5 5 5 5 20 20 20 20 20 5 5 5 5	DMFA DMFA DMFA DMFA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 1 1 1 1 1	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891 4690.863 2695.653 5029.318 2964.375 4540.673 2848.039 4994.425 3097.556 3096.222 1130.108 3223.721 1391.525 3367.514 735.8303 3063.38
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 3	FO F	5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	W W W V V V W W W V V V W W W W W W W W	20 20 20 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 5 5 5 5	DMFA DMFA DMFA DMFA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 1 1 1 1	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891 4690.863 2695.653 5029.318 2964.375 4540.673 2848.039 4994.425 3097.556 3096.222 1130.108 3223.721 1391.525 3367.514 735.8303 3063.38 1264.4
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 3	Four eure ure ure ure ure ure ure ure ure	5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	W W W V V V V W W W V V V V W W W V V V V W W W V V V V W W W V V V V W W W V V V V W W W V V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W W V V V V W W W W W V V V V W W W W W V V V V W W W W W V V V V W W W W W V V V V W W W W W W V V V V W W W W W W V V V V W	20 20 20 5 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 5 5 5 5	DMFA DMFA DMFA DMFA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 1 1 1 1 1	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2659.653 5029.318 2964.375 4540.673 2848.039 4994.425 3097.556 3096.222 1130.108 3223.721 1391.525 3367.514 735.8303 3063.38 1264.4, 3286.707
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 3	FOURT CECECE CECECECECECECECECECECECECECECEC	5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 5	W W W V V V W W W V V V W W W V V V W W W V V V V W W W W V V V W W W W V V V W W W W W V V V W W W W W V V V W W W W W V V V W W W W W V V V W W W W W V V V W W W W W V V V W W W W W V V V W W W W W V V V W W W W W W W W W V V V W	20 20 20 5 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMFA DMFA DMFA DMFA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 1 1 1 1	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2658.891 4690.863 2695.653 5029.318 2964.375 4540.673 2848.039 4994.425 3097.556 3096.222 1130.108 3223.721 1391.525 3367.514 735.8303 3063.38 1264.4 3286.707 1162.79
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 3 3 3 3	Four eure ure ure ure ure ure ure ure ure	5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	W W W V V V V W W W V V V V W W W V V V V W W W V V V V W W W V V V V W W W V V V V W W W V V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W V V V V W W W W W V V V V W W W W W V V V V W W W W W V V V V W W W W W V V V V W W W W W V V V V W W W W W W V V V V W W W W W W V V V V W	20 20 20 5 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 5 5 5 5	DMFA DMFA DMFA DMFA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000 4000 4000 400	1000 1000 1000 1000 1000 1000 1000 100	100 100 100 100 100 100 100 100 100 100	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 1 1 1 1 1	4879.942 2891.03 4912.866 3036.185 4437.605 2880.5 5043.313 2875.502 4705.449 3012.273 5032.286 2659.653 5029.318 2964.375 4540.673 2848.039 4994.425 3097.556 3096.222 1130.108 3223.721 1391.525 3367.514 735.8303 3063.38 1264.4, 3286.707

3	Fe	20	w	20	DMFA	4000	1000	120	1	1286.159
3	Cu	20	w	20	DMFA	4000	1000	120	i	3052.865
3	Fe	5	V	5	DMAA	4000	1000	120	. 1	1140.058
3	Cu	5	V	5	DMAA	4000	1000	120	1	2545.555
3	Fe	20	V	5	DMAA	4000	1000	120	1	1075.588
3	Cu	20	٧	5	DMAA	4000	1000	120	1	3170.971
3	Fe	5	W	5	DMAA	4000	1000	120	1	1025.795
3	Cu	5	W	5	DMAA	4000	1000	120	1	3205.365
3	Fe	20	W	5	DMAA	4000	1000	120	1	1144.007
3	Çu	20	w	5	DMAA	4000	1000	120	1	3073.614
3	Fe	5	V	20	DMAA	4000	1000	120	1	991.2687
3 3	Cu Fe	5 20	V V	20	DMAA	4000	1000	120	1	2875.273
3	Cu	20	v	20 20	DMAA DMAA	4000 4000	1000	120	1	987.423
3	Fø	5	w	20	DMAA	4000	1000 1000	. 120 120	1 1	3169.661 1393.893
3	Cu	5	w	20	DMAA	4000	1000	120	1	3361.081
3	Fe	20	w	20	DMAA	4000	1000	120	1	1464.002
3	Cu	20	w	20	DMAA	4000	1000	120	i	3221.897
4	Fe	5	V	5	DMFA	500	1000	120	2	3562.027
4	Cu	5	V .	5	DMFA	500	1000	120	2	1169.025
4	Fe	20	V	5	DMFA	500	1000	120	2	3065.418
4	Cu	20	V	5	DMFA	500	1000	120	2	1179.965
4	Fe	5	W	5	DMFA	500	1000	120	2	3167.984
4	Cu	5	W	5	DMFA	500	1000	120	2	1297.288
4	Fe	20	W	5	DMFA	500	1000	120	2	2967.498
4	Cu	20	W	5	DMFA	500	1000	120	2	502.1629
4	Fe	5	V	20	DMFA	500	1000	120	2	3156.959
4	က	5	V	20	DMFA	500	1000	120	2	1254.915
4	Fe	20	V	20	DMFA	500	1000	120	2	3403.2
4 4	Cu Fe	20 5	V W	20	DMFA	500	1000	120	. 2	1311.478
4	Cu	5	w	20 20	DMFA DMFA	500 500	1000 1000	120 120	2	3215.089
4	Fe	20	w	20	DMFA	500 500	1000	120	2 2	801.7368 2463.873
4	Cu	20	w	20	DMFA	500	1000	120	2	1286.28
4	Fe	5	Ÿ	5	DMAA	500	1000	120	2	3225.547
	. •	-	•	•	0.170 0 1	000	1000	120	-	0220.0 7 7
4	Cu	5	V	5	DMAA	500	1000	120	2	1027.837
4 4	Cu Fe	5 20	v v	5 5	DMAA DMAA	500	1000 1000	120 120	2 2	1027.837 3455.892
			v v	5 5		500 500			2 2	
4	Fe Cu Fe	20 20 5	v v	5 5 5	DMAA DMAA DMAA	500 500 500	1000 1000 1000	120 120 120	2 2 2	3455.892 1167.907 3040.422
4 4 4 4	Fe Cu Fe Cu	20 20 5 5	V V W	5 5 5 5	DMAA DMAA DMAA DMAA	500 500 500 500	1000 1000 1000 1000	120 120 120 120	2 2 2 2	3455.892 1167.907 3040.422 1625.673
4 4 4 4	Fe Cu Fe Cu Fe	20 20 5 5 20	V V W W	5 5 5 5	DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500	1000 1000 1000 1000 1000	120 120 120 120 120	2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228
4 4 4 4 4	Fe Cu Fe Cu Fe Cu	20 20 5 5 20 20	V W W W	5 5 5 5	DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500	1000 1000 1000 1000 1000 1000	120 120 120 120 120 120	2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155
4 4 4 4 4 4	Fe Cu Fe Cu Fe Cu	20 20 5 5 20 20 5	>>	5 5 5 5 5 20	DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000	120 120 120 120 120 120 120	2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219
4 4 4 4 4 4	Fe Cu Fe Cu Fe Cu	20 20 5 5 20 20 5	V W W W V	5 5 5 5 5 20 20	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000	120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461
4 4 4 4 4 4 4 4	Fe Cu Fe Cu Fe Cu Fe	20 20 5 5 20 20 5 5 20	>	5 5 5 5 5 20 20 20	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73
4 4 4 4 4 4 4 4	Fe Cu Fe Cu Fe Cu Fe Cu	20 20 5 5 20 20 5 5 5 20	>	5 5 5 5 5 20 20 20 20	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012
4 4 4 4 4 4 4 4 4	Fe Cu Fe Cu Fe Cu Fe Cu Fe	20 20 5 5 20 20 5 5 20 20 5 5	>	5 5 5 5 5 20 20 20 20 20	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964
4 4 4 4 4 4 4 4	Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu	20 20 5 5 20 20 5 5 20 20 5 5 5	>>	5 5 5 5 5 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468
4 4 4 4 4 4 4 4 4 4 4	Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5	>> \$ \$ \$ \$ > > > \$ \$ \$	5 5 5 5 5 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955
4 4 4 4 4 4 4 4 4 4	Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu	20 20 5 5 20 20 5 5 20 20 5 5 5	>>	5 5 5 5 5 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468
4 4 4 4 4 4 4 4 4 4 4	Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5	V V W W V V V V W W W W W	5 5 5 5 5 5 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624
4 4 4 4 4 4 4 4 4 4 4 4 4	Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5	V V W W V V W W W V V W W W V W W W V W W W W V W	5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624 1285.104
4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Fe Cu	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5	V V W W V V W W W W V V V V V V V V V V	5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 5 5	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624 1285.104 3131.439
4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Fe Cu Fe	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 5	V W W W V V W W W W V V V V V V V V V V	5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 5 5 5 5	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624 1285.104 3131.439 1191.938
4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Fe Cu	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 5	V V W W V V V V W W W W W W W W W W W W	5 5 5 5 5 5 20 20 20 20 20 20 20 5 5 5 5	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624 1285.104 3131.439 1191.938 3019.846
4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Fe Cu Fe	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	V V W W V V V V W W W W W W W W W W W W	5 5 5 5 5 5 5 20 20 20 20 20 20 20 5 5 5 5	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624 1285.104 3131.439 1191.938 3019.846 1598.604 3058.827 1111.198
4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Fe Cu	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 20 5 20 20 20 20 20 20 20 20 20 20 20 20 20	<pre></pre>	5 5 5 5 5 5 5 20 20 20 20 20 20 20 5 5 5 5	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624 1285.104 3131.439 1191.938 3019.846 1598.604 3058.827 1111.198 3429.221
4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Fe Cu Fe	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 20 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	V V W W V V V V W W W V V V V W W W V V V V W W W V V V V V W W W V V V V W W W V V V V W W W V V V V W W W V V V V W W W V V V V W W W V V V V W W W V V V V W W W V V V V W W W V V V V W W W V V V V V W W W V V V V V W W W V V V V V W W W V V V V V W W W W V V V V V W W W W V V V V V W W W W V V V V V W W W W V V V V V W W W W W V V V V V W W W W W V V V V V W W W W W W V V V V W W W W W W V V V V V W	5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 5 5 5 5	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624 1285.104 3131.439 1191.938 3019.846 1598.604 3058.827 1111.198 3429.221 1584.459
4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Fe Cu	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 5	V V W W W V V V W W W W V V V V V W W W W V V V V V W W W W W W V V V V V W	5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624 1285.104 3131.439 1191.938 3019.846 1598.604 3058.827 1111.198 3429.221 1584.459 3624.455
4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Fe Cu Fe	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	<pre></pre>	5 5 5 5 5 5 20 20 20 20 20 20 20 20 5 5 5 5	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624 1285.104 3131.439 1191.938 3019.846 1598.604 3058.827 1111.198 3429.221 1584.459 3624.455 1352.145
4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Fe Cu	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	<pre></pre>	5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624 1285.104 3131.439 1191.938 3019.846 1598.604 3058.827 1111.198 3429.221 1584.459 3624.455 1352.145 3281.384
4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Fe Cu e Cu	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 20 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	<pre></pre>	5 5 5 5 5 5 20 20 20 20 20 20 20 20 5 5 5 5	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624 1285.104 3131.439 1191.938 3019.846 1598.604 3058.827 1111.198 3429.221 1584.459 3624.455 1352.145 3281.384 1323.115
4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Fe Cu	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 20 5 5 5 5	<pre></pre>	5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 5 5 5 5	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624 1285.104 3131.439 1191.938 3019.846 1598.604 3058.827 1111.198 3429.221 1584.459 3624.455 1352.145 3281.384 1323.115 3189.967
4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Fe Cu	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	<pre></pre>	5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624 1285.104 3131.439 1191.938 3019.846 1598.604 3058.827 1111.198 3429.221 1584.459 3624.455 1352.145 3281.384 1323.115 3189.967 1523.089
4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Fe Cu	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	<pre></pre>	5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624 1285.104 3131.439 1191.938 3019.846 1598.604 3058.827 1111.198 3429.221 1584.459 3624.455 1352.145 3281.384 1323.115 3189.967 1523.089 3211.642
4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Fe Cu	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	<pre></pre>	5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624 1285.104 3131.439 1191.938 3019.846 1598.604 3058.827 1111.198 3429.221 1584.459 3624.455 1352.145 3281.384 1323.115 3189.967 1523.089 3211.642 1342.161
4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Fe Cu	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 5	<pre></pre>	5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624 1285.104 3131.439 1191.938 3019.846 1598.604 3058.827 1111.198 3429.221 1584.459 3624.455 1352.145 3281.384 1323.115 3189.967 1523.089 3211.642 1342.161 3207.565
4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Fe Cu	20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	<pre></pre>	5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMAA DMAA DMAA DMAA	500 500 500 500 500 500 500 500	1000 1000 1000 1000 1000 1000 1000 100	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3455.892 1167.907 3040.422 1625.673 2649.228 1075.155 3454.219 1726.461 3407.73 1391.012 3375.964 1620.468 3347.955 1227.624 1285.104 3131.439 1191.938 3019.846 1598.604 3058.827 1111.198 3429.221 1584.459 3624.455 1352.145 3281.384 1323.115 3189.967 1523.089 3211.642 1342.161

5	Cu	20	w	5	DMAA	500	1200	100	1	4260.867
5	Fe	5	V	20	DMAA	500	1200	100	1	1845.083
5	Cu	5	V	20	DMAA	500	1200	100	1	4220.054
5	Fe	20	٧	20	DMAA	500	1200	100	1	2422.747
5	Cu	20	V	20	DMAA	500	1200	100	1	4208.349
5	Fe	5	W	20	DMAA	500	1200	100	1	2481.61
5	Cu	5	W	20	DMAA	500	1200	100	1	4414.644
5	Fe	20	W	20	DMAA	590	1200	100	1	2320.681
5	Cu	20	W	20	DMAA	500	1200	100	1	4131.439
5	Fe	5	V	5	DMFA	4000	1200	100	1	3764.029
5	Cu	5	V	5	DMFA	4000	1200	100	1	2456.474
5	Fe	20	V	5	DMFA	4000	1200	100	1	4196.127
5	Cu	20	V	5	DMFA	4000	1200	100	1	2489.818
5	Fe	5	W	5	DMFA	4000	1200	s. 100	1	4326.255
5 5	Cu	5 20	W W	5	DMFA	4000	1200	100	1	1798.646
5	Fe Cu	20	w	5 5	DMFA	4000	1200	100	1	4552.989
5	Fe	5	v	20	DMFA DMFA	4000 4000	1200 1200	100 100	1 1	2438.734 4899.729
5	Cu	5	v	20	DMFA	4000	1200	100	1	4699.729 1766.201
5	Fe	20	v ·	20	DMFA	4000	1200	100	1	3853.274
5	Cu	20	v	20	DMFA	4000	1200	100	i 1	2205.384
5	Fe	5	w	20	DMFA	4000	1200	100	1	4483.398
5	Cu	5	w	20	DMFA	4000	1200	100	1	2193.717
5	Fe	20	w	20	DMFA	4000	1200	100	1	3915.764
5	Cu	20	w	20	DMFA	4000	1200	100	1	2130.307
5	Fø	5	v	5	DMAA	4000	1200	100	1	4268.58
5	Cu	5	v	5	DMAA	4000	1200	100	i	2449.769
5	Fe	20	v	5	DMAA	4000	1200	100	1	4051.658
5	Cu	20	v	5	DMAA	4000	1200	100	1	2319.5
5	Fe	5	w	5	DMAA	4000	1200	100	1	4182.63
5	Cu	5	w	5	DMAA	4000	1200	100	ì	1913.637
5	Fe	20	W	5	DMAA	4000	1200	100	1	4171.779
5	Cu	20	W	5	DMAA	4000	1200	100	1	1788.613
6	Fe	5	V	20	DMAA	4000	1200	100	1	4304.112
6	Cu	5	٧	20	DMAA	4000	1200	100	1	2340.053
6	Fe	20	٧	20	DMAA	4000	1200	100	1	3973.3
6	Cu	20	V	20	DMAA	4000	1200	100	1	2242.964
6 6	Cu Fe	20 5	v w	20 20	DMAA DMAA	4000 4000	1200 1200	100 100	1	2242.964 4220.131
6 6 6	Cu Fe Cu	20 5 5	v w w	20 20 20	DMAA DMAA DMAA	4000 4000 4000	1200 1200 1200	100 100 100	1 1 1	2242.964 4220.131 2029.409
6 6 6	Cu Fe Cu Fe	20 5 5 20	W W W	20 20 20 20	DMAA DMAA DMAA DMAA	4000 4000 4000 4000	1200 1200 1200 1200	100 100 100 100	1 1 1	2242.964 4220.131 2029.409 4474.279
6 6 6 6	Cu Fe Cu Fe Cu	20 5 5 20 20	V W W W	20 20 20 20 20	DMAA DMAA DMAA DMAA DMAA	4000 4000 4000 4000 4000	1200 1200 1200 1200 1200	100 100 100 100 100	1 1 1 1	2242.964 4220.131 2029.409 4474.279 2185.812
6 6 6 6	Cu Fe Cu Fe Cu Fe	20 5 5 20 20 5	>	20 20 20 20 20 20 5	DMAA DMAA DMAA DMAA DMAA DMFA	4000 4000 4000 4000 4000 500	1200 1200 1200 1200 1200 1200	100 100 100 100 100 100	1 1 1 1 1 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736
6 6 6 6 6	Cu Fe Cu Fe Cu Fe	20 5 5 20 20 5 5	>	20 20 20 20 20 20 5	DMAA DMAA DMAA DMAA DMAA DMFA DMFA	4000 4000 4000 4000 4000 500 500	1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100	1 1 1 1 1 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12
6 6 6 6 6 6	Cu Fe Cu Fe Cu Fe	20 5 5 20 20 5 5	V W W W V V	20 20 20 20 20 5 5	DMAA DMAA DMAA DMAA DMAA DMFA DMFA	4000 4000 4000 4000 4000 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100	1 1 1 1 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772
6 6 6 6 6 6 6	Cu Fe Cu Fe Cu Fe Cu	20 5 5 20 20 5 5 20	<pre></pre>	20 20 20 20 20 5 5 5	DMAA DMAA DMAA DMAA DMAA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456
6 6 6 6 6 6 6 6	Cu Fe Cu Fe Cu Fe Cu Fe	20 5 5 20 20 5 5 20 20 5	<pre></pre>	20 20 20 20 20 5 5 5 5	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100	1 1 1 1 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89
6 6 6 6 6 6 6 6 6	Cu Fe Cu Fe Cu Fe Cu Fe Cu	20 5 5 20 20 5 5 20 20 5	>	20 20 20 20 5 5 5 5 5	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562
6 6 6 6 6 6 6 6 6 6	Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe	20 5 5 20 20 5 5 20 20 5 5	>	20 20 20 20 20 5 5 5 5 5 5	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059
6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	Cu Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe	20 5 5 20 20 5 5 20 20 5 5 20	>	20 20 20 20 20 5 5 5 5 5 5 5 5 5	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892
6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	Cu Fe u e	20 5 5 20 5 5 20 20 5 5 20 5 20	>	20 20 20 20 5 5 5 5 5 5 5 5 5 5	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214
6 6 6 6 6 6 6 6 6 6 6 6 6 6	Cu e u e u e u e u e u e cu e cu e cu e	20 5 5 20 5 5 20 20 5 5 5 20 5 5 5	>	20 20 20 20 5 5 5 5 5 5 5 5 5 5 20 20	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636
6 6 6 6 6 6 6 6 6 6 6 6 6 6	Cu Fe u e cu	20 5 5 20 20 5 5 20 5 5 20 5 5 20	>	20 20 20 20 20 5 5 5 5 5 5 5 5 5 20 20 20	DMAA DMAA DMAA DMAA DMAA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 3355.542
6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	Cu Fe u e u e u e u e cu Fe u e u e cu Fe u e cu Fe u	20 5 5 20 20 5 5 20 5 5 20 20 5 5 20 20	>	20 20 20 20 5 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 3355.542 5019.747
6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	Cu e u e u e u e u e u e u e u e u e u e	20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20	>	20 20 20 20 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 3355.542 5019.747 3747.147
6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	Cu Fe u e u e u e u e cu Fe u e u e cu Fe u e cu Fe u	20 5 5 20 20 5 5 20 5 5 20 20 5 5 20 20	>	20 20 20 20 5 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 3355.542 5019.747 3747.147 5053.546
6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	Cue u e u e u e u e u e u e cue u e u e cue cu	20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20	>	20 20 20 20 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 3355.542 5019.747 3747.147 5053.546 3082.532
6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	Cue u e u e u e u e u e u e u e u e u e	20 5 5 20 5 5 20 5 5 20 20 5 5 20 20 5 5 20 20 5	>	20 20 20 20 5 5 5 5 5 5 5 5 5 5 20 20 20 20 20 5 5 5 5	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 3355.542 5019.747 3747.147 5053.546
6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	Cu e u e u e u e u e u e u e u e u e cre cre cre cre cre cre cre cre cre c	20 5 5 20 20 5 5 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 5	>	20 20 20 20 5 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 5 5 5 5	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 3355.542 5019.747 3747.147 5053.546 3082.532 5055.11
6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	Cueueueueueueueueueueueueueueueueueueue	20 5 5 20 5 5 20 5 5 20 20 5 5 20 20 5 5 20 20 5	>	20 20 20 20 5 5 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 3355.542 5019.747 3747.147 5053.546 3082.532 5055.11
6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	Cueueueueueueueueueueueueueueueueueueue	20 5 5 20 20 5 5 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 5	> 3 3 3 3 > > > > 3 3 3 3 5 5 5 5 5 5 5	20 20 20 20 5 5 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMAA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 3355.542 5019.747 3747.147 5053.546 3082.532 5055.11 2903.681 4726.624
6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	Cue u e u e u e u e u e u e u e u e u e	20 5 5 20 20 5 5 20 5 5 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 5 5 20 5 5 20 5 5 5 20 5 5 5 5	> 3 3 3 3 > > > > 3 3 3 3 > > > 5 3 3 5 > > > 5 3 3 5 > > > 5 3 5 5 > > > 5 3 5 5 > > > 5 3 5 5 5 > > 5 5 5 5	20 20 20 20 5 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 3355.542 5019.747 3747.147 5053.546 3082.532 5055.11 2903.681 4726.624 3378.448
6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	Cue u e u e u e u e u e u e u e u e u e	20 5 5 20 20 5 5 20 5 5 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 5 5 20 5 5 5 20 5 5 5 5	>\$\$\$\$>>>>\$\$\$\$	20 20 20 20 5 5 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 3355.542 5019.747 3747.147 5053.546 3082.532 5055.11 2903.681 4726.624 3378.448 5179.236
666666666666666666666666666666666666666	C F C F C F C F C F C F C F C F C F C F	20 5 5 20 20 5 5 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 5 5 5 20 5 5 20 5 5 20 5 5 5 20 5 5 5 20 5 5 5 5	>\$\$\$\$>>>>\$\$\$\$	20 20 20 20 20 5 5 5 5 5 5 5 5 5 5 5 5 5	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 3355.542 5019.747 3747.147 5053.546 3082.532 5055.11 2903.681 4726.624 3378.448 5179.236 3013.919
666666666666666666666666666666666666666	CHEU EU E	20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 20 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	>\$\$\$\$>>>>\$\$\$\$	20 20 20 20 20 5 5 5 5 5 5 5 5 5 5 5 5 5	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 3355.542 5019.747 3747.147 5053.546 3082.532 5055.11 2903.681 4726.624 3378.448 5179.236 3013.919 4803.361
666666666666666666666666666666666666666	Cue u e u e u e u e u e u e u e u e u e	20 5 5 20 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 20 5 5 20 5 5 20 5 5 20 5 5 5 20 5 5 5 20 5 5 5 20 5 5 5 5	>\$\$\$\$>>>>\$\$\$\$>	20 20 20 20 5 5 5 5 5 5 5 5 5 5 5 5 5 5	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 33555.542 5019.747 3747.147 5053.546 3082.532 5055.11 2903.681 4726.624 3378.448 5179.236 3013.919 4803.361 3213.767
666666666666666666666666666666666666666	CHEU PUPUPUPUPUPUPUPUPUPUPUPUPUPUPUPUPUPUP	20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 5 20 5 5 5 20 5 5 5 20 5 5 5 5	> \$ \$ \$ \$ > > > \$ \$ \$ \$ \$ > > > \$ \$ \$ \$	20 20 20 20 20 5 5 5 5 5 5 5 5 5 5 5 5 5	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 3355.542 5019.747 3747.147 5053.546 3082.532 5055.11 2903.681 4726.624 3378.448 5179.236 3013.919 4803.361 3213.767 5545.379 3585.461 4672.836
666666666666666666666666666666666666666	C F C F C F C F C F C F C F C F C F C F	20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 5 20 5 5 5 20 5 5 5 5	>\$\$\$\$>>>>\$\$\$\$>>>>	20 20 20 20 20 5 5 5 5 5 5 5 5 5 5 5 5 5	DMAA DMAA DMAA DMAA DMAA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 3355.542 5019.747 3747.147 5053.546 3082.532 5055.11 2903.681 4726.624 3378.448 5179.236 3013.919 4803.361 3213.767 5545.379 3585.461 4672.836 3238.526
666666666666666666666666666666666666666	Cue u e u e u e u e u e u e u e u e u e	20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 5 20 5 20 5 5 20 5 5 5 20 5 5 20 5 5 5 5	>\$\$\$\$>>>>\$\$\$\$>>>>	20 20 20 20 20 5 5 5 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMAA DMAA DMAA DMAA DMFA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 3355.542 5019.747 3747.147 5053.546 3082.532 5055.11 2903.681 4726.624 3378.448 5179.236 3013.919 4803.361 3213.767 5545.379 3585.461 4672.836 3238.526 5161.146
666666666666666666666666666666666666666	C F C F C F C F C F C F C F C F C F C F	20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 20 5 5 5 20 5 5 5 20 5 5 5 5	>\$\$\$\$>>>>\$\$\$\$>>>>	20 20 20 20 20 5 5 5 5 5 5 5 5 5 5 5 5 5	DMAA DMAA DMAA DMAA DMAA DMFA DMFA DMFA	4000 4000 4000 4000 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	100 100 100 100 100 100 100 100 100 100	1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2242.964 4220.131 2029.409 4474.279 2185.812 3200.736 5251.12 2941.772 5348.456 3216.89 5601.562 3213.059 5455.892 3248.214 4972.636 3355.542 5019.747 3747.147 5053.546 3082.532 5055.11 2903.681 4726.624 3378.448 5179.236 3013.919 4803.361 3213.767 5545.379 3585.461 4672.836 3238.526

_	_			_					_	
7	Cu	20	V	5	DMFA	4000	1200	120	1	3393.315
7	Fe	5	W	5	DMFA	4000	1200	120	1	1403.261
7	Cu	5	W	5	DMFA	4000	1200	120	1	3555.009
7	Fe	20	W	5	DMFA	4000	1200	120	1	1308.279
7	Cu	20	W	5	DMFA	4000	1200	120	1	3512.98
7	Fe	5	V	20	DMFA	4000	1200	120	1	1284.812
7	Cu	5	٧	20	DMFA	4000	1200	120	1	3435.316
7	Fe	20	V	20	DMFA	4900	1200	120	1	1694.665
7	Cu	20	٧	20	DMFA.	4000	1200	120	1	3496.463
7	Fe	5	W	20	DMFA	4000	1200	120	1	1143.947
7	Cu	5	W	20	DMFA	4000	1200	120	1	3456.876
7	Fe	20	W	20	DMFA	4000	1200	120	1	1617.505
7	Cu	20	W	20	DMFA	4000	1200	120	1	3879.49
7	Fø	5	v	5	DMAA	4000	1200	120	i	1273.745
7	Cu	5	v	5	DMAA	4000	1200	120	i	3382.074
7	Fe	20	v	5	DMAA	4000	1200	120	i	881.0287
7	Cu	20	v	5	DMAA	4000	1200	120	i	3104.413
7	Fe	5	w	5	DMAA	4000	1200	120	i	1395,572
7	Cu	5	w	5	DMAA	4000	1200	120	i	3141.805
7	Fe	20	w ·	5	DMAA	4000	1200	120	1	1774.357
7	Cu	20	w	5	DMAA	4000	1200	120	1	3413.901
8	Fe	5	v	20	DMAA	4000	1200	120	1	1649,139
8	Cu	5	V	20	DMAA	4000	1200	120	1	3368.794
8	Fe	20	V	20	DMAA	4000	1200	120	1	1824.133
8	Cu	20	V	20	DMAA	4000	1200	120	1	3660.883
8	Fe	5	W	20	DMAA	4000	1200	120	1	1179.379
8	Cu	5	W	20	DMAA	4000	1200	120	1	3628.204
8	Fe	20	W	20	DMAA	4000	1200	120	1	1293.674
8	Cu	20	W	20	DMAA	4000	1200	120	1	3019.058
8	Fe	5	V	5	DMFA	500	1200	120	2	2990.086
8	Cu	5	٧	5	DMFA	500	1200	120	2	1029.93
8	Fe	20	٧	5	DMFA	500	1200	120	2	3062.541
8	Cu	20	٧	5	DMFA	500	1200	120	2	1242.527
8	Fe	5	W	5	DMFA	500	1200	120	2	3147.093
8	Cu	5	W	5	DMFA	500	1200	120	2	1316.01
_	_			_						
8	Fe	20	W	5	DMFA	500	1200	120	2	3127.044
8	Cu	20	W	5	DMFA	500	1200	120	2	1729.955
8 8	Cu Fe	20 5	w v	5 20	DMFA DMFA	500 500	1200 1200	120 120	2 2	1729.955 3923.339
8 8 8	Cu Fe Cu	20 5 5	w v v	5 20 20	DMFA	500 500 500	1200	120	2 2 2	1729.955
8 8 8 8	Cu Fe Cu Fe	20 5 5 20	w v v	5 20 20 20	DMFA DMFA DMFA DMFA	500 500 500 500	1200 1200	120 120	2 2 2 2	1729.955 3923.339
8 8 8	Cu Fe Cu	20 5 5	w v v	5 20 20 20 20	DMFA DMFA DMFA	500 500 500 500 500	1200 1200 1200	120 120 120	2 2 2	1729.955 3923.339 1251.202
8 8 8 8	Cu Fe Cu Fe	20 5 5 20	w v v	5 20 20 20	DMFA DMFA DMFA DMFA	500 500 500 500 500 500	1200 1200 1200 1200	120 120 120 120	2 2 2 2	1729.955 3923.339 1251.202 3291.114
8 8 8 8	Cu Fe Cu Fe Cu	20 5 5 20 20 5	w	5 20 20 20 20	DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500	1200 1200 1200 1200 1200	120 120 120 120 120	2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178
8 8 8 8 8	Cu Fe Cu Fe Cu Fe	20 5 5 20 20 5	w v v v	5 20 20 20 20 20	DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500	1200 1200 1200 1200 1200 1200	120 120 120 120 120 120	2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405
8 8 8 8 8	Cu Fe Cu Fe Cu Fe	20 5 5 20 20 5	w > > > w	5 20 20 20 20 20 20	DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120	2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929
8 8 8 8 8 8	Cu Fe Cu Fe Cu Fe	20 5 5 20 20 5 5 5	w >> >> w	5 20 20 20 20 20 20 20	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78
8 8 8 8 8 8 8	Cu Fe Cu Fe Cu Fe Cu	20 5 5 20 20 5 5 20 20	w > > > w w w	5 20 20 20 20 20 20 20 20	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165
8 8 8 8 8 8 8	Cu Fe Cu Fe Cu Fe Cu Fe	20 5 5 20 20 5 5 20 20	w	5 20 20 20 20 20 20 20 20 20	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566
8 8 8 8 8 8 8 8	Cu Fe Cu Fe Cu Fe Cu Fe Cu	20 5 5 20 20 5 5 20 20 5 5	w	5 20 20 20 20 20 20 20 20 5 5	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768
8 8 8 8 8 8 8 8 8	Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe	20 5 5 20 20 5 5 20 20 5 5 20	% > > > % % % > > >	5 20 20 20 20 20 20 20 5 5 5 5	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317
8 8 8 8 8 8 8 8 8	Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe	20 5 5 20 20 5 5 20 20 5 5 5 20	<pre>% >>>> % % >>>> %</pre>	5 20 20 20 20 20 20 20 5 5 5 5	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu	20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5	% > > > % % % > > >	5 20 20 20 20 20 20 20 5 5 5 5 5	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Cu Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe	20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5	<pre>% >> >> % % % % % % % % % % % % % % %</pre>	5 20 20 20 20 20 20 20 5 5 5 5 5 5	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464 3243.016
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu Fe Cu	20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 20 20	<pre>% > > ></pre>	5 20 20 20 20 20 20 5 5 5 5 5 5 5	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464 3243.016 1659.831
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Cu Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe	20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 20 5 5 5 5	% > > >	5 20 20 20 20 20 20 5 5 5 5 5 5 5 5 5	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464 3243.016 1659.831 3832.087
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Cu Fe Fe Cu Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe	20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 5	% >>>> %%% >>>>> %%% >>>	5 20 20 20 20 20 20 5 5 5 5 5 5 5 5 20 20 20	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464 3243.016 1659.831 3832.087 1434.119
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Cu Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe	20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 5	% > > > % % % > > > % % % > > >	5 20 20 20 20 20 20 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464 3243.016 1659.831 3832.087 1434.119 3898.378
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	CU FE U FE	20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 5	\$>>>>\$\$\$>>>>	5 20 20 20 20 20 20 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMAA DMA	500 500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3168.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464 3243.016 1659.831 3832.087 1434.119 3898.378 1514.125
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Cu Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe Fe	20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 5	8>>>>8	5 20 20 20 20 20 20 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464 3243.016 1659.831 3832.087 1434.119 3898.378 1514.125 3320.126
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Cu Fe u e Cu Fe Cu	20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 5	<pre>% >> ></pre>	5 20 20 20 20 20 20 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464 3243.016 1659.831 3832.087 1434.119 3898.378 1514.125 3320.126 1269.161
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Cu Fe u e Cu Fe	20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 5	<pre>%>>>></pre>	5 20 20 20 20 20 20 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.766 3181.766 3184.317 3483.545 1483.464 3243.016 1659.831 3832.087 1434.119 3898.378 1514.125 3320.126 1269.161 3552.422
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Cu Fe u e Cu Fe u e Cu Fe u e Cu Fe u e Cu Fe Cu	20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	<pre>%>>>></pre>	5 20 20 20 20 20 20 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464 3243.016 1659.831 3892.087 1434.119 3898.378 1514.125 3320.126 1269.161 3552.422 1408.177
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Cu Fe u e C Fe C F	20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 5	\$>>>>\$\$\$\$>>>>\$\$\$\$>	5 20 20 20 20 20 20 5 5 5 5 5 5 5 5 5 5	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464 3243.016 1659.831 3832.087 1434.119 3898.378 1514.125 3320.126 1269.161 3552.422 1408.177
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	CU F	20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 5	\$>>>>\$\$\$\$>>>>\$\$\$\$>>	5 20 20 20 20 20 20 5 5 5 5 5 5 5 5 5 5	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464 3243.016 1659.831 3832.087 1434.119 3898.378 1514.125 320.126 1269.161 3552.422 1408.177 1330.367 3233.872
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	CU FC C F	20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 5	8>>>>8888>>>>	5 20 20 20 20 20 20 5 5 5 5 5 5 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464 3243.016 1659.831 3832.087 1434.119 3898.378 1514.125 3320.126 1269.161 3552.422 1408.177 1330.367 3233.872 1119.671
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Cu e u e u e u e u e u e u e u e u e u e	20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 5	8>>>>\$888>>>>	5 20 20 20 20 20 20 5 5 5 5 5 20 20 20 20 20 5 5 5 5	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464 3243.016 1659.831 3832.087 1434.119 3898.378 1514.125 3320.126 1269.161 3552.422 1408.177 1330.367 3233.872 1119.671
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	CU F	20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	\$>>>>\$\$\$\$>>>>\$	5 20 20 20 20 20 20 5 5 5 5 5 5 20 20 20 20 5 5 5 5	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464 3243.016 1659.831 3832.087 1434.119 3898.378 1514.125 3320.126 1269.161 3552.422 1408.177 1330.367 3233.872 1119.671 3565.294 1540.59
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	CU F	20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 20 20 5 5 5 5	8>>>>8888>>>>	5 20 20 20 20 20 20 5 5 5 5 5 5 20 20 20 20 5 5 5 5	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.766 3181.766 3181.766 3184.317 3483.545 1483.464 3243.016 1659.831 3832.087 1434.119 3898.378 1514.125 3320.126 1269.161 3552.422 1408.177 1330.367 3233.872 1119.671 3565.294 1540.59 3197.359
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	CU F	20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	8>>>>8888>>>>>8888	5 20 20 20 20 20 20 5 5 5 5 5 5 5 20 20 20 20 5 5 5 5	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464 3243.016 1659.831 3832.087 1434.119 3898.378 1514.125 3320.126 1269.161 3552.422 1408.177 1330.367 3233.872 1119.671 3565.294 1540.59 3197.359 1421.148
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	CU FC C F	20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 5 5 20 20 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	8>>>>8888>>>>	5 20 20 20 20 20 20 5 5 5 5 5 5 5 20 20 20 20 5 5 5 5	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464 3243.016 1659.831 3832.087 1434.119 3898.378 1514.125 3320.126 1269.161 3552.422 1408.177 1330.367 3233.872 1119.671 3565.294 1540.59 3197.359 1421.148 3467.429
8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	CU F	20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 20 20 5 5 5 20 20 20 20 20 20 20 20 20 20 20 20 20	8>>>>8888>>>>>8888	5 20 20 20 20 20 20 5 5 5 5 5 5 5 20 20 20 20 5 5 5 5	DMFA DMFA DMFA DMFA DMFA DMFA DMFA DMFA	500 500 500 500 500 500 500 500	1200 1200 1200 1200 1200 1200 1200 1200	120 120 120 120 120 120 120 120 120 120	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1729.955 3923.339 1251.202 3291.114 1309.178 3166.405 1079.929 3399.78 1317.061 3249.165 1310.566 3181.768 1384.317 3483.545 1483.464 3243.016 1659.831 3832.087 1434.119 3898.378 1514.125 3320.126 1269.161 3552.422 1408.177 1330.367 3233.872 1119.671 3565.294 1540.59 3197.359 1421.148

10

In this iteration, each of the metal acetylacetonates, the DMAA, and the DMFA is made up as a stock solution in phenol. An appropriate quantity of each stock solution is then combined using a Hamilton MicroLab 4000 laboratory robot into a single vial for mixing. For example, the stock solutions to produce rows 1, 65, 129,193, 257, 321, 385, and 449 or TABLE 12, are 0.01 molar Pd(acetylacetonate), 0.01 molar each of Fe(acetylacetonate) and V(acetylacetonate) and 5 molar DMFA. Ten ml of each stock solution is produced by manual weighing and mixing. Aliquots of the stock solutions are measured as follows in TABLE 13. The mixture is stirred using a miniature magnetic stirrer.

10

15

20

TABLE 13

25 microliters	
125 microliters	
125 microliters	
25 microliters	
700 microliters	• • •
	125 microliters 125 microliters 25 microliters

In the second iteration, pressure chamber reactor 54 is heated and pressurized to the conditions shown as Block 1 in TABLE 7. The procedure described as iteration 1 is repeated in the system described with reference to FIG 3 and FIG. 4 with the species of TABLE 10. This process is repeated until all the block conditions have been run.

The performance of each vial is given in the column "TON" of TABLE 13. These results are then analyzed using a "General Linear Model" (GLM) routine in Minitab software. A GLM routine performs analysis of variance (ANOVA) on any specified mathematical model potentially describing a relationship between control factors and response. The routine determines which terms of the model actually have a statistically significant influence on response. The GLM routine is set to calculate an Analysis of Variance (ANOVA) for all main effects, 2-way interactions, and 3-way interactions in data. In a factorial design, an effect of a factor is the average change in response when the value of that factor is changed from its low level to its high level. The effect is a main effect when it is calculated without including the influence of other factors. A 2-way interaction mathematically describes change in the effect of one factor when a second factor is changed from its low level to its high level. A 3-way interaction mathematically describes change in the effect of one factor when two other factors simultaneously are changed from respective low levels to respective high levels.

The ANOVA in this Example is given in TABLE 14.

TABLE 14

Pressure*CS	1	11954	11954	11954	0.146	0.702	
Temperature*Time	1	33291520	33291520	33291520	407.672	0.000	YES
Temperature*M1	1	43430	43430	43430	0.532	0.466	
Temperature*M2	1	94767	94767	94767	1.160	0.282	
Temperature*CS	1	90412	90412	90412	1.107	0.293	
Time*M1	1	1491	1491	1491	0.018	0.893	
Time*M2	1	93605	93605	93605	1.146	0.285	
Time*CS	1	76043	76043	76043	0.931	0.335	
M1*M2	1	77799	77799	77799	0.953	0.330	
M1*CS	1	169760	169760	169760	2.079	0.150	
M2*CS	1	407136	407136	407136	4.986	0.026	
M1 amt*M2 amt*CS amt	1	361079	361079	361079	4.422	0.036	
M1 amt*M2 amt*Pressure	1	21432	21432	21432	0.262	0.609	
M1 amt*M2 amt*Temperature	1	271	271	271	0.003	0.954	
M1 amt*M2 amt*Time	1	13991	13991	13991	0.171	0.679	
M1 amt*M2 amt*M1	1	281433	281433	281433	3.446	0.064	
M1 amt*M2 amt*M2	1	1	1	1	0.000	0.997	
M1 amt*M2 amt*CS	1	116073	116073	116073	1.421	0.234	
M1 amt*CS amt*Pressure	1	114627	114627	114627	1.404	0.237	
M1 amt*CS amt*Temperature	1	466	466	466	0.006	0.940	
M1 amt*CS amt*Time	1	69157	69157	69157	0.847	0.358	
M1 amt*CS amt*M1	1	164860	164860	164860	2.019	0.156	
M1 amt*CS amt*M2	1	14698	14698	14698	0.180	0.672	
M1 amt*CS amt*CS	1	334131	334131	334131	4.092	0.044	
M1 amt*Pressure*Temperature	1	235	235	235	0.003	0.957	
M1 amt*Pressure*Time	1	167809	167809	167809	2.055	0.153	
M1 amt*Pressure*M1	1	8172	8172	8172	0.100	0.752	
M1 amt*Pressure*M2	1	4377	4377	4377	0.054	0.817	
M1 amt*Pressure*CS	1	6356	6356	6356	0.078	0.780	
M1 amt*Temperature*Time	1	67161	67161	67161	0.822	0.365	
M1 amt*Temperature*M1	1	194664	194664	194664	2.384	0.123	
M1 amt*Temperature*M2	1	569	569	569	0.007	0.934	
M1 amt*Temperature*CS	1	11	11	11	0.000	0.991	
M1 amt*Time*M1	1	6489	6489	6489	0.079	0.778	
M1 amt*Time*M2	1	30862	30862	30862	0.378	0.539	

Marie								
Mart			-	•	-		P	Significant at P<0.01
Samin								
Pressure								
Temperature								VEQ
Time	Temperature	1						
M2	-		31205785	31205785	31205785			
Samt	·				•		0.000	YES
MI amit'N2 amit 1 27038 27038 0.331 0.585 MI amit'Pressure 1 58292 58292 59292 0.714 0.389 MI amit'Pressure 1 51467 61467 61467 0.753 0.389 MI amit'Time 1 110415 110415 110415 110415 120248 MI amit'Time 1 14335 34335 34320 0.248 MI amit'N2 1 232880 232880 2.249 0.022 MI amit'CS 1 26046 260446 3.189 0.075 MI amit'CS 1 79627 79627 79627 0.075 0.324 M2 amit'CS amit'Temperature 1 477 477 477 0.006 0.939 M2 amit'M2 1 61525 8125 1553 0.999 0.318 M2 amit'M2 1 61525 8125 8125 0.999 0.753 M2 amit'M2 1 61525 8125								
Mile amit CS amit 1 SE292 SE292 5202 0.714 0.389 MI amit Temperature 1 26926 26926 26926 0.330 0.688 MI amit Time 1 110415 1.10415 1.352 0.248 MI amit MI 1 24335 34335 34335 0.420 0.517 MI amit MI 1 223280 230880 2.449 0.075 MI amit MI 1 24335 34335 34355 0.420 0.517 MI amit MI 1 24335 34335 34355 0.420 0.514 MI amit MI 1 226046 260446		-						
Mi amit*Pressure 1 61487 61467 61467 0.753 0.388 Mi amit*Ime 1 15928 28928 26928 26928 0.330 0.588 Mi amit*Ime 1 110415 110415 1.332 0.246 Mi amit*Mi 1 34335 34335 34335 0.420 0.517 Mi amit*CS 1 260448 260448 260448 36048 3.189 0.075 M2 amit*CS amit 1 79827 79827 79827 0.975 0.324 M2 amit*Tensesure 1 4174 31447 341447 341447 4181 0.042 M2 amit*Mi 1 14190 14190 14190 0.174 0.677 M2 amit*Mi 1 14190 14190 0.141 0.677 M2 amit*Mi 1 14190 14190 0.143 0.521 M2 amit*Mi 1 18155 8155 0.099 0.753 CS amit*Tenperature								
Miles Miles 1104415 1104415 1104415 1104415 1104415 1104415 1104415 1104415 1104415 1104415 1104415 1104415 1104415 1104415 1104415 1104415 1104415 210441 22880 22880 22880 0.928 0.075 Miles 11 232880 232880 22880 22880 0.075 M2 amit CS 1 76927 79827 79827 0.975 0.324 M2 amit Temperature 1 4774 777 477 477 477 477 477 477 477 477 477 477 477 477 477 477 478 478 41447 41810 0.042 41810 0.042 41810 0.042 41810 0.042 41810 0.042 41810 0.042 40272 0.060 0.059 0.059 0.059 0.059 0.059 0.059 0.059 0.059 0.058 0.058 0.058 0			61467	61467				
MI ann'tMI 1 34335 34335 34335 0.420 0.517 MI ann'tCS 1 250846 250840 20880 2089 0.092 MI ann'tCS ann 1 250446 2						0.330	0.566	
MI amit**CS 1 280480 232880 232880 23280 23280 20048 M2 amit**CS amit**CS 1 260464 260446 260446 260446 3189 0.075 M2 amit**Perssure 1 79827 79827 79827 79827 0.975 0.324 M2 amit**Perssure 1 4774 477 478 474 418 0.061 0.599 0.318 M2 amit*M2 1 14180 14180 14180 0.174 0.507 0.507 M2 amit*M2 1 15180 31533 31533 31749 0.413 0.525 M2 amit*Pessure 1 255416 2594								
Maint'CS amt								
M2 amt"Cs amt M2 amt"Pressure 1 341447 341447 341447 4 1814 0.042 M2 amt"Temperature 1 477 477 0.006 0.939 M2 amt"Temperature 1 125869 125869 125869 0.1140 0.174 0.215 M2 amt"TM M3 16153 81553 81553 0.999 0.318 M3 amt"GS 0.999 0.3990 0.590 M3 amt"GS 0.990 0.753 M3 amt"GS 0.990 0.753 M3 amt"GS 0.990 0.753 M3 amt"GS 0.990 0.753 M3 amt"GS 0.990 0.783 M3 amt"GS 0.990 0.783 M3 amt"GS 0.990 0.783 M3 amt"GS 0.990 0.783 M3 amt"GS 0.990 0.990 0.990 0.990 M3 amt"GS 0.990 0.990 0.990 M3 amt"GS 0.990 0.990 0.990 M3 amt"GS 0.990 0.990 0.990 M3 amt"M3 0.990 0.990 0.990 M3 amt"GS 0.990 0.990 0.990 M3 amt"M3 0.990 0.990 0.990 0.990 M3 amt"M3 0.990 0.99								
M2 amil'Temperature 1 125869 125869 125869 125869 0.000 0.00	M2 amt*CS amt	1	79627	79627				
M2 amt"Time						4.181	0.042	•
M2 amt*M1								
M2 ant"M2	· · · · · · · · · · · · · · · · · · ·							
M2 amt*CS								
CS amtTenperature 1 33749 33749 0.413 0.821 CS amtTime 1 295416 295416 3.618 0.058 CS amtTime 1 7438 7438 7438 0.091 0.763 CS amtTM1 1 132568 132568 1.623 0.203 CS amtTCS 1 23702 23702 0.290 0.590 Pressure*Temperature 1 40272 40272 0.272 0.483 0.483 Pressure*Time 1 38 38 38 0.000 0.983 Pressure*M1 1 253770 253770 3.108 0.075 M1 amt*Time*CS 1 163612 163612 163612 2.004 0.158 M1 amt*M1*CS 1 77397 77397 77397 0.948 0.331 M1 amt*M2*CS 1 1421 11421 11421 1140 0.079 M2 amt*CS amt*Tressure* 1 6344 6344 6344 <td< td=""><td>M2 amt*CS</td><td></td><td></td><td></td><td></td><td></td><td></td><td>,</td></td<>	M2 amt*CS							,
CS amtTimel 1 7438 7438 7438 0.091 0.763 CS amtM1 1 132568 132568 132580 0.457 0.500 CS amtM2 1 37280 37280 37280 0.457 0.500 CS amtM2 1 23702 23702 23702 0.990 0.990 Pressure*Temperature 1 40272 40272 0.0272 0.0290 0.983 Pressure*Ime 1 38 38 38 0.000 0.983 Pressure*IM1 1 263870 253770 3.108 0.079 Pressure*IM2 1 260899 260899 250899 3.195 0.075 M1 amt*M1*M2 1 77397 77397 77397 0.948 0.331 M1 amt*M1*CS 1 158409 59409 59409 0.727 0.394 M2 amt*CS amt*Treessure 1 6344 6344 6344 0.078 0.781 M2 amt*CS amt*M1 <		1	33749	33749	33749			
CS amt*M1 1 132568 132568 132568 1.623 0.203 CS amt*M2 1 37280 37280 0.457 0.500 CS amt*CS 1 23702 23702 0.290 0.590 Pressure*Temperature 1 40272 40272 0.290 0.590 Pressure*Time 1 38 38 38 0.000 0.983 Pressure*Time 1 253770 253770 253770 3.108 0.079 Pressure*M1 1 253770 253770 253770 3.108 0.079 Pressure*M2 1 260899 260899 3.195 0.075 M1 amt*Time*CS 1 163612 163612 163612 2.004 0.158 M1 amt*M1*M2 1 77397 77397 77397 0.948 0.331 M1 amt*M1*M2 1 77397 77397 77397 0.948 0.331 M1 amt*M1*CS 1 11421 11421 11421 0.140 0.709 M1 amt*M2*CS 1 59409 59409 5.727 0.394 M2 amt*CS amt*Temperature 1 0 0 0 0 0.000 1.000 M2 amt*CS amt*Time 1 70019 70019 0.857 0.355 M2 amt*CS amt*M1 1 89887 89887 89887 1.101 0.295 M2 amt*CS amt*M1 1 89887 89887 89887 1.101 0.295 M2 amt*CS amt*CS 1 1476 0.225 M2 amt*CS amt*M2 1 120523 120523 1.26523 1.476 0.225 M2 amt*Pressure*M1 1 7373 7373 7373 0.090 0.764 M2 amt*Pressure*M1 1 7373 7373 7373 0.090 0.764 M2 amt*Pressure*Time 1 14716 14716 14716 1680 0.671 M2 amt*Pressure*M1 1 7373 7373 7373 0.090 0.764 M2 amt*Pressure*Time 1 14716 14716 14716 1680 0.671 M2 amt*Pressure*M1 1 7373 7373 7373 0.090 0.764 M2 amt*Pressure*M1 1 7383 6233 6233 0.076 0.782 M2 amt*Timperature*M2 1 94448 94448 94448 1.157 0.283 M2 amt*Timperature*M1 1 77055 77055 77055 0.944 0.332 M2 amt*Timperature*M2 1 94448 9448 9448 1.157 0.283 M2 amt*Timperature*M2 1 94448 9448 9448 9448 1.157 0.283 M2 amt*Timperature*M2 1 92288 2.2868 2.807 0.107 0.043 M2 amt*Timperature*M2 1 92289 0.299 0.299 0.299 0.299 0.299 0.299 0.299 0.299 0.299 0.299 0.299							0.058	
CS amt"M2 1 37280 37280 37280 0.457 0.500 CS amt"CS 1 23702 23702 0.290 0.590 Pressure Temperature 1 40272 40272 40272 0.290 0.590 Pressure Temperature 1 38 38 38 0.000 0.983 Pressure Time 1 38 38 38 0.000 0.983 Pressure Time 1 260899 260899 260899 3.195 0.075 M1 amt"Time*CS 1 163612 163612 163612 2.004 0.158 M1 amt"M1"M2 1 77397 77397 77397 0.948 0.331 M1 amt"M1"CS 1 11421 11421 0.140 0.709 M1 amt"M2"CS 1 59409 59409 59409 0.727 0.394 M2 amt"CS amt"Temperature 1 0 0 0 0.000 1.000 M2 amt"CS amt"Time 1 70019 70019 70019 0.857 0.355 M2 amt"CS amt"M1 1 89887 89887 1.101 0.295 M2 amt"CS amt"M2 1 120523 120523 1.476 0.225 M2 amt"CS amt"M2 1 190090 190090 0.328 0.128 M2 amt"CS amt"M2 1 17373 7373 7373 0.090 0.764 M2 amt"CS amt"M1 1 89887 8479 0.104 0.747 M2 amt"CS amt"M2 1 130523 120523 1.476 0.225 M2 amt"CS amt"M1 1 7373 7373 7373 0.090 0.764 M2 amt"Pressure*Time 1 14716 14716 0.180 0.671 M2 amt"Pressure*Time 1 14716 14716 0.180 0.671 M2 amt"Pressure*Time 1 62831 6881 6831 0.329 0.567 M2 amt"Pressure*Time 1 62831 6881 6831 0.329 0.567 M2 amt"Pressure*Time 1 62633 6233 0.076 0.782 M2 amt"Time M1 1 77055 77055 77055 0.944 0.332 M2 amt"Time M1 1 77055 77055 77055 0.944 0.332 M2 amt"Time M1 1 77055 77055 77055 0.944 0.332 M2 amt"Time M1 1 77055 77055 77055 0.944 0.332 M2 amt"Time M1 1 77055 77055 77055 0.944 0.332 M2 amt"Time M1 1 77055 77055 77055 0.944 0.332 M2 amt"Time M1 1 77055 77055 77055 0.944 0.332 M2 amt"Time M1 1 77055 77055 77055 0.944 0.332 M2 amt"Time M1 1 77055 77055 77055 0.944 0.332 M2 amt"Time M2 1 84561 84561 0.055 0.310 M3 amt"Time M2 1 84561 84561 0.055 0.040 M3 amt"Time M2 1 84561 84561 0.055 0.056 M3 amt"Time M2 1 84561 84561 0.055 0.056 M3 amt"Time M2 1 84561 84561 0.055 0								
CS amt*CS								
Pressure*Temperature 1 40272 40272 0.493 0.483 Pressure*Imme 1 38 38 38 0.000 0.983 Pressure*M1 1 253770 253770 253770 3.108 0.079 Pressure*M2 1 260899 260899 260899 3.195 0.075 M1 amt*Time*CS 1 163612 163612 163612 2.004 0.158 M1 amt*M1*M2 1 77397 77397 77397 0.948 0.331 M1 amt*M1*CS 1 11421 11421 11421 11421 0.140 0.709 M1 amt*M2*CS 1 59409 59409 59409 0.727 0.394 M2 amt*CS amt*Pressure 1 6344 6344 0.078 0.781 M2 amt*CS amt*Time 1 70019 70019 70019 0.857 0.355 M2 amt*CS amt*M1 1 89887 89887 89887 1.010 0.295 M2 amt*CS amt*M1 1 89887 89887 89887 1.010 0.295 M2 amt*CS amt*M2 1 120523 120523 120523 1.476 0.225 M2 amt*Cs amt*Time 1 190090 190090 190090 2.328 0.128 M2 amt*Pressure*Time 1 14716 14716 14716 0.180 0.671 M2 amt*Pressure*M2 1 163557 16357 10.300 0.764 M2 amt*Pressure*M2 1 163557 16357 10.200 0.655 M2 amt*Temperature*M1 1 626 626 626 0.008 0.930 M2 amt*Temperature*M1 1 6263 12633 126523 0.567 M2 amt*Temperature*M2 1 1244 124 124 124 124 124 124 124 124	· · · · · · · · · · · · · · · · · · ·							
Pressure*Time	Pressure*Temperature	1						
Pressure*M2 1 260899 260899 260899 3.195 0.075 M1 amt*Time*CS 1 163612 163612 2.004 0.158 M1 amt*M1*M2 1 77397 77397 77397 0.948 0.331 M1 amt*M1*CS 1 11421 11421 0.140 0.709 M1 amt*M2*CS 1 59409 59409 0.727 0.394 M2 amt*CS amt*Pressure 1 6344 6344 6344 0.078 0.781 M2 amt*CS amt*Time 1 0 0 0 0.000 1.000 M2 amt*CS amt*Time 1 70019 70019 70019 0.857 0.355 M2 amt*CS amt*Time 1 170019 70019 70019 0.857 0.355 M2 amt*CS amt*M1 1 89987 89887 89887 1.101 0.295 M2 amt*CS amt*CS 1 8479 8479 8479 0.104 0.747 M2 amt*Pressure*Temperature 1 190090 190090 190090 2.328 0.128 M2 amt*Pressure*Time 1 14716 14716 14716 0.180 0.671 M2 amt*Pressure*M1 1 7373 7373 7373 0.090 0.764 M2 amt*Pressure*M1 1 7373 7373 7373 0.090 0.764 M2 amt*Pressure*M1 1 7373 7373 7373 0.090 0.764 M2 amt*Pressure*W1 1 16357 16357 16357 0.200 0.655 M2 amt*Temperature*M1 1 626 626 626 0.008 0.930 M2 amt*Temperature*M1 1 626 626 626 0.008 0.930 M2 amt*Temperature*M1 1 626 626 626 0.008 0.930 M2 amt*Temperature*M2 1 94448 94448 94448 1.157 0.283 M2 amt*Temperature*M2 1 94448 94448 94448 1.157 0.283 M2 amt*Temperature*M2 1 94448 94448 94448 1.157 0.283 M2 amt*Temperature*M2 1 9438 9438 9439 0.490 0.764 M2 amt*Temperature*M2 1 94448 94448 94448 1.157 0.283 M2 amt*Temperature*M2 1 9438 9439 0.490 0.764 M2 amt*Temperature*M2 1 9438 9448 94448 1.157 0.283 M2 amt*Temperature*M2 1 9438 9439 0.490 0.764 M2 amt*Temperature*M2 1 9448 9448 9448 1.157 0.283 M2 amt*Temperature*M2 1 9448 9448 9448 1.157 0.283 M2 amt*Temperature*M2 1 9438 9438 9448 9448 1.157 0.043 M2 amt*Temperature*M2 1 9438 9448 9448 9448 1.157 0.283 M2 amt*Temperature*M3 1 9438 9438 9448 9448 1.157 0.283 M2 amt*Temperature*M3 1 9438 9438 9448 9448 9448 1.157 0.283 M2 amt*Temperature*M3 1 9438 9438 9448 9448 9448 9448 9448 9448			1		38	0.000		
M1 amt"Time"CS								
M1 amt*M1*M2	Pressure M2	1	260899	260899	260899	3.195	0.075	
M1 amt*M1*CS	M1 amt*Time*CS	1	163612	163612	163612	2.004	0.158	
M1 amt*M2*CS						0.948	0.331	
M2 amt*CS amt*Pressure 1 6344 6344 6344 0.078 0.781 M2 amt*CS amt*Temperature 1 0 0 0 0.000 1.000 M2 amt*CS amt*Time 1 70019 70019 70019 0.857 0.355 M2 amt*CS amt*M1 1 89887 89887 89887 1.101 0.225 M2 amt*CS amt*M2 1 120523 120523 120523 1.476 0.225 M2 amt*CS amt*CS 1 8479 8479 0.104 0.747 M2 amt*Pressure*Temperature 1 190090 190090 2.328 0.128 M2 amt*Pressure*M1 1 7373 7373 0.090 0.6671 M2 amt*Pressure*M2 1 16357 16357 16357 0.200 0.655 M2 amt*Temperature*Time 1 26831 26831 26831 0.090 0.900 M2 amt*Temperature*M2 1 94448 94448 1.157 0.283 M2 amt*Temperature*M2								•
M2 amt*CS amt*Temperature 1 0 0 0.000 1.000 M2 amt*CS amt*Time 1 70019 70019 0.857 0.355 M2 amt*CS amt*M1 1 89887 89887 89887 1.01 0.295 M2 amt*CS amt*M2 1 120523 120523 120523 1.476 0.225 M2 amt*CS amt*CS 1 8479 8479 8479 0.104 0.747 M2 amt*Pressure*Temperature 1 190090 190090 2.328 0.128 M2 amt*Pressure*Time 1 14716 14716 0.140 0.671 M2 amt*Pressure*M1 1 7373 7373 7373 0.090 0.764 M2 amt*Pressure*CS 1 35027 35027 35027 0.200 0.655 M2 amt*Temperature*M1 1 62831 26831 26831 0.329 0.567 M2 amt*Temperature*M1 1 628 626 626 0.008 0.930 M2 amt*Temperature*M2								
M2 amt*CS amt*Time 1 70019 70019 70019 0.857 0.355 M2 amt*CS amt*M1 1 89887 89887 8887 1.101 0.295 M2 amt*CS amt*M2 1 120523 120523 120523 1,476 0.225 M2 amt*CS amt*CS 1 8479 8479 8479 0.104 0.747 M2 amt*Pressure*Temperature 1 190090 190090 190090 2.328 0.128 M2 amt*Pressure*Im 1 14716 14716 14716 0.180 0.671 M2 amt*Pressure*M1 1 7373 7373 7373 0.090 0.764 M2 amt*Pressure*CS 1 35027 35027 35027 0.429 0.513 M2 amt*Temperature*M1 1 26831 26831 0.329 0.567 M2 amt*Temperature*M2 1 94448 94448 94448 1,157 0.283 M2 amt*Time*M1 1 77055 77055 77055 0.944 0.332								
M2 amit*CS amit*M1 1 89887 89887 1.101 0.295 M2 amit*CS amit*M2 1 120523 120523 120523 1.014 0.225 M2 amit*CS amit*CS 1 8479 8479 8479 0.104 0.747 M2 amit*Pressure*Temperature 1 190090 190090 190090 0.2328 0.128 M2 amit*Pressure*M1 1 14716 14716 14716 0.180 0.671 M2 amit*Pressure*M2 1 16357 16357 16357 0.200 0.655 M2 amit*Pressure*M2 1 16357 16357 16357 0.200 0.655 M2 amit*Pressure*M2 1 26831 26831 26831 0.329 0.567 M2 amit*Temperature*M1 1 626 626 626 0.008 0.930 M2 amit*Temperature*M2 1 94448 94448 94448 1.157 0.283 M2 amit*Time*M1 1 77055 77055 77055 0.944	M2 amt*CS amt*Time	1	70019		_			
M2 amt*CS amt*CS				89887	89887	1.101		
M2 amt*Pressure*Temperature 1 190090 190090 2.328 0.128 M2 amt*Pressure*Time 1 14716 14716 14716 0.180 0.671 M2 amt*Pressure*M1 1 7373 7373 7373 0.090 0.764 M2 amt*Pressure*M2 1 16357 16357 16357 0.200 0.655 M2 amt*Pressure*CS 1 35027 35027 0.429 0.513 M2 amt*Temperature*Time 1 26831 26831 0.329 0.567 M2 amt*Temperature*M1 1 626 626 626 0.008 0.930 M2 amt*Temperature*M2 1 94448 94448 94448 1.157 0.283 M2 amt*Time*M1 1 77055 77055 77055 0.944 0.332 M2 amt*Time*M1 1 77055 77055 77055 0.944 0.332 M2 amt*Time*M1 1 77055 77055 77055 0.944 0.332 M2 amt*Time*M2 1 6233 6233 6233 0.076 0.782 M2 amt*Time*CS 1 337817 337817 337817 4.137 0.043 M2 amt*M1*M2 1 38653 38653 38653 0.076 0.782 M2 amt*M1*M2 1 38653 38653 38653 0.076 0.782 M2 amt*M1*CS 1 23751 23751 0.291 0.590 M2 amt*M1*CS 1 3270 3270 0.040 0.842 CS amt*Pressure*Temperature* 1 84561 84561 1.035 0.310 CS amt*Pressure*Time 1 212868 212868 2.607 0.107 CS amt*Pressure*M1 1 34495 34495 34495 0.422 0.516 CS amt*Pressure*M1 1 535239896 535239896 535239896 6554.288 0.000 YES CS amt*Temperature*M1 1 535239896 535239896 6554.288 0.000 YES CS amt*Temperature*M2 1 4708 4708 4708 0.058 0.810 CS amt*Temperature*M2 1 4708 4708 4708 0.058 0.810 CS amt*Temperature*M2 1 4708 4708 4708 0.058 0.810								
M2 amt*Pressure*Time		•						
M2 amt*Pressure*M1								
M2 amt*Pressure*M2 1 16357 16357 16357 0.200 0.655 M2 amt*Pressure*CS 1 35027 35027 35027 0.428 0.513 M2 amt*Temperature*Time 1 26831 26831 26831 0.329 0.567 M2 amt*Temperature*M1 1 626 626 626 0.008 0.930 M2 amt*Temperature*CS 1 94448 94448 94448 1.157 0.283 M2 amt*Time*M1 1 77055 77055 77055 0.944 0.332 M2 amt*Time*M2 1 6233 6233 6233 0.076 0.782 M2 amt*Time*CS 1 337817 337817 337817 0.043 M2 amt*M1*M2 1 38653 38653 38653 0.473 0.492 M2 amt*M2*CS 1 3270 3270 3270 0.040 0.842 CS amt*Pressure*Temperature 1 84561 84561 84561 1.035 0.310 CS amt*Pressure*M2 1 20299 20299 0.249 0.618	M2 amt*Pressure*M1	1						
M2 amt*Temperature*Time 1 26831 26831 0.329 0.567 M2 amt*Temperature*M1 1 626 626 626 0.008 0.930 M2 amt*Temperature*M2 1 94448 94448 1.157 0.283 M2 amt*Temperature*CS 1 1212 1212 0.015 0.903 M2 amt*Time*M1 1 77055 77055 77055 0.944 0.332 M2 amt*Time*M2 1 6233 6233 6233 0.076 0.782 M2 amt*Time*M2 1 337817 337817 337817 0.043 M2 amt*Time*CS 1 337817 337817 337817 4.137 0.043 M2 amt*M1*M2 1 38653 38653 38653 0.473 0.492 M2 amt*M1*CS 1 23751 23751 0.291 0.590 M2 amt*M2*CS 1 3270 3270 0.040 0.842 CS amt*Pressure*Temperature 1 84561 84561 1.035 0.310 CS amt*Pressure*Time 1 212868 212868 212868 2.607 0.107 CS amt*Pressure*M1 1 34495 34495 0.422 0.516 CS amt*Pressure*CS 1 12034 12034 12034 0.147 0.701 CS amt*Temperature*Time 1 174636 174636 174636 2.139 0.144 CS amt*Temperature*M2 1 4708 4708 4708 0.058 0.810 CS amt*Temperature*CS 1 331 331 0.004 0.949	M2 amt*Pressure*M2							
M2 amt*Temperature*M1						0.429	0.513	
M2 amt*Temperature*M2	· ·							
M2 amt*Temperature*CS	•							
M2 amt*Time*M1								
M2 amt*Time*M2 1 6233 6233 0.076 0.782 M2 amt*Time*CS 1 337817 337817 4.137 0.043 M2 amt*M1*M2 1 38653 38653 38653 0.473 0.492 M2 amt*M1*CS 1 23751 23751 0.291 0.590 M2 amt*M2*CS 1 3270 3270 0.040 0.842 CS amt*Pressure*Temperature 1 84561 84561 84561 1.035 0.310 CS amt*Pressure*Time 1 212868 212868 2.607 0.107 CS amt*Pressure*M1 1 34495 34495 0.422 0.516 CS amt*Pressure*CS 1 12034 12034 12034 0.147 0.701 CS amt*Temperature*Time 1 174636 174636 174636 2.139 0.144 CS amt*Temperature*M2 1 4708 4708 4708 0.058 0.810 CS amt*Temperature*CS 1 331 331 331 0.004 0.949								•
M2 amt*M1*M2					6233			
M2 amt*M1*CS								
M2 amt*M2*CS								
CS amt*Pressure*Temperature 1 84561 84561 84561 1.035 0.310 CS amt*Pressure*Time 1 212868 212868 212868 2.607 0.107 CS amt*Pressure*M1 1 34495 34495 0.422 0.516 CS amt*Pressure*M2 1 20299 20299 0.249 0.618 CS amt*Pressure*CS 1 12034 12034 0.147 0.701 CS amt*Temperature*Time 1 174636 174636 174636 2.139 0.144 CS amt*Temperature*M1 1 535239896 535239896 6554.288 0.000 YES CS amt*Temperature*M2 1 4708 4708 4708 0.058 0.810 CS amt*Temperature*CS 1 331 331 0.004 0.949								
CS amt*Pressure*Time								
CS amt*Pressure*M1 1 34495 34495 0.422 0.516 CS amt*Pressure*M2 1 20299 20299 0.249 0.618 CS amt*Pressure*CS 1 12034 12034 0.147 0.701 CS amt*Temperature*Time 1 174636 174636 174636 2.139 0.144 CS amt*Temperature*M1 1 535239896 535239896 535239896 6554.288 0.000 YES CS amt*Temperature*M2 1 4708 4708 0.058 0.810 CS amt*Temperature*CS 1 331 331 0.004 0.949								
CS amt*Pressure*CS							0.516	
CS amt*Temperature*Time 1 174636 174636 2.139 0.144 CS amt*Temperature*M1 1 535239896 535239896 535239896 6554.288 0.000 YES CS amt*Temperature*M2 1 4708 4708 0.058 0.810 CS amt*Temperature*CS 1 331 331 0.004 0.949								
CS amt*Temperature*M1 1 535239896 535239896 535239896 6554.288 0.000 YES CS amt*Temperature*M2 1 4708 4708 0.058 0.810 CS amt*Temperature*CS 1 331 331 0.004 0.949								
CS amt*Temperature*M2 1 4708 4708 4708 0.058 0.810 CS amt*Temperature*CS 1 331 331 0.004 0.949								YES
CS amt*Temperature*CS 1 331 331 0.004 0.949	· ·							
Со впіт піпетмі 1 112874 112874 112874 1.382 0.240	•						0.949	
	Co ami: Hime:M1	7	112874	112874	112874	1.382	0.240	

10

CS amt*Time*M2	1	1469	1469	1469	0.018	0.893	
CS amt*Time*CS	1	804	804	804	0.010	0.921	
CS amt*M1*M2	1	7578 5	75785	75785	0.928	0.336	
CS amt*M1*CS	1	22036	22036	22036	0.270	0.604	
CS amt*M2*CS	1	34743	34743	34743	0.425	0.515	
Pressure*Temperature*Time	1	950930	950930	950930	11.645	0.001	YES
Pressure*Temperature*M1	1	18226	18226	18226	0.223	0.637	
Pressure*Temperature*M2	1	11544	11544	11544	0.141	0.707	
Pressure*Temperature*CS	1	67428	67428	67428	0.826	0.364	
Pressure*Time*M1	1	310071	310071	310071	3.797	0.052	
Pressure*Time*M2	1	10784	10784	10784	0.132	0.717	
Pressure*Time*CS	1	2008	2008	2008	0.025	0.875	
Pressure*M1*M2	1	12343	12343	12343	0.151	0.698	
Pressure*M1*CS	1	14220	14220	14220	0.174	0.677	
Pressure*M2*C\$	1	67936	67936	67936	0.832	0.362	
Temperature*Time*M1	1	221695	221695	221695	2.715	0.100	
Temperature*Time*M2	1	38	38	38	0.000	0.983	
Temperature*Time*CS	1	10	10	10	0.000	0.991	
Temperature*M1*M2	1	24040	24040	24040	0.294	0.588	
Temperature*M1*CS	1	257092	257092	257092	3.148	0.077	
Temperature*M2*CS	1	848	848	848	0.010	0.919	
Time*M1*M2	1	53303	53303	53303	0.653	0.420	
Time*M1*CS	1	44080	44080	44080	0.540	0.463	
Time*M2*CS	1	7295	7295	7295	0.089	0.765	
M1*M2*CS	1	319669	319669	319669	3.915	0.049	
Ептог	382	31195094	31195094	81662.55			
Total	511	885328201					

The column "Significant at P<0.01" of TABLE 14 defines the factors and interactions in the model, which have a statistically significant effect on the response with a probability of incorrect decision of less than 1%. The column shows that only 5 of the 129 possible main effects, 2-way interactions, and 3-way interactions have a significant effect on the TON. It is noted that a 3-way interaction (CS amt*Temperature*M1) has the largest influence on the TON (FIG.5).

This Example shows that the disclosed method can perform large numbers of experiments and can sort out variables in a combinatorial experiment to detect key process interactions. From this interaction a favorable condition for obtaining high (>5500) TON is determined as shown in TABLE 15.

:

5

10

15

TABLE 15

Factor	Identity	Amount
M1	Cu	Any
M2	Any	Any
CS	Any	500
Pressure		Any
Temperature		100C
Time		2 hr

The interaction identifies a unique condition in which two formulation variables (M1 = Cu and CS amount = 500) generate a very high level of TON only when the temperature is at 100° C.

It will be understood that each of the elements described above, or two or more together, may also find utility in applications differing from the types described herein. While the invention has been illustrated and described as embodied in a sequential high-throughput screening method and system, it is not intended to be limited to the details shown, since various modifications and substitutions can be made without departing in any way from the spirit of the present invention. For example, robotic equipment can be used to prepare samples and various types of parallel analytical screening methods can be incorporated. As such, further modifications and equivalents of the invention herein disclosed may occur to persons skilled in the art using no more than routine experimentation, and all such modifications and equivalents are believed to be within the spirit and scope of the invention as defined by the following claims.